

Curtiss-Wright Technical Information Bulletin

August 2023

The following topics are discussed in this Bulletin:

- “GENERAL INFORMATION” ON PAGE 1
- “TECHNICAL INFORMATION” ON PAGE 1
- “DOCUMENT CHANGES” ON PAGE 2
- “HARDWARE STATUS” ON PAGE 3
- “APPENDIX” ON PAGE 4
- “ACRONYMS” ON PAGE 26

General information

The Acra KAM-500 Databook (HW/BK/0002) comprises data sheets for released Acra KAM-500 products. The latest release of the Acra KAM-500 Databook is dated 10 Aug. 2023.

A Recorders Databook (HW/BK/0039) comprising data sheets for released Recorder products is now available. This new release of the Recorders Databook is dated 2 May 2023.

The Applications Handbook (HW/BK/0005) comprises technical notes for Curtiss-Wright products. The latest release of the Applications Handbook is dated 5 Jul. 2023.

DAS Studio 3 is the setup software for data acquisition units, network switches, recorders and ground stations. The latest release of DAS Studio 3 is version 3.4.26.

AXN Databook release

The AXN Databook (BK/0046 | 10 Aug. 2023) comprising data sheets for all currently released AXN chassis and modules is now available.

The AXN Databook can be requested from Curtiss-Wright support (dub_customersupport@curtisswright.com).

Technical information

New FAQs

N/A

New technical notes

Since the previous bulletin was issued the following technical notes are available:

N/A

New user guides

N/A

Training

Curtiss-Wright offers a variety of training courses, within SVS/TRN/100, which help delegates develop the skills needed to configure the various Curtiss-Wright products. Standard courses include introductory training for Acra KAM-500 airborne data acquisition hardware, and advanced training on Acra KAM-500 and Axon airborne data acquisition systems. Course content can be standard, user-definable or a combination of both. We strongly recommend training for those who are not familiar with Curtiss-Wright equipment.

Document changes

The content of the following documents has been revised since the previous release of the bulletin.

Acra KAM-500 products

| Product - reference | Action |
|---|---|
| KAM/TCG/105 14 Jul. 2023 DST/Z/025 | Corrected Figures 1 and 4 to show TTL_IN as TTL_IN_A. In the General specifications table, removed the "-12V" row from Power consumption; revised the total power accordingly. Removed the "Output resistance" row from Tables 8, 9, 10, and 11. In the "GPS antenna" section, removed reference to the RFE/AEG/001 antenna and noted the antenna that is currently recommended; clarified that when estimating system power the max current drawn theoretically by the antenna should be added to the KAM/TCG/105 +12V current figure. Removed the "Warm power-up" and "Reacquisition" section. Removed RFE/AEG/001 from the Related products table. |
| KAM/TCG/106 18 Jul. 2023 DST/AG/014 | Corrected Figures 1 and 4 to show TTL_IN as TTL_IN_A. Removed the "Output resistance" row from Tables 9, 10, and 11. Removed the "Output resistance" row from Tables 8, 9, 10, and 11. In the "GPS antenna" section, removed reference to the RFE/AEG/001 antenna and noted the antenna that is currently recommended; clarified that when estimating system power the max current drawn theoretically by the antenna should be added to the KAM/TCG/105 +12V current figure. Removed the "Warm power-up" section. Removed RFE/AEG/001 from the Related products table. |

AXN products

| Product - reference | Action |
|---|---|
| AXN/ADC/401 19 Jul. 2023 DST/AB/019 | In Table 6, Theoretical worst case aliasing values, moved all values in the MIN column to the MAX column. |

DAS Studio 3

The current release is 3.4.26. Features of the software include the following:

- Discovers, configures, manages and programs Data Acquisition Units (DAUs), recorders, switches, ground station boards, and third party equipment
- Functionality can be extended through external plug-in applications
- Supports the open metadata standard

GSX-500

GTS SDK 3.3

The current release of GTS SDK is 3.3. Features of GTS SDK 3.3 include the following:

- Set up using a XidML 3.0 file
- Acquisition of minor PCM frame data of up to 20Mbps for each channel
- GTS SDK 3 real-time API is interrupt driven, no polling is performed
- Direct memory access data transfer relieving CPU power
- Minor frame loopback function for testing without external PCM stream
- Code samples for Borland C++, Visual Studio C++ .NET and Visual Studio C# .NET
- Driver for GTS-500 boards

For details of known GSX-500 issues, see "GTS SDK 3.3" on page 22.

Hardware status

Released products

Since the previous bulletin, the data sheet for the following product has been given a standard release:

AXN products

| Product - reference | Description | Features |
|---|--|---|
| AXN/ICP/401/B 17 Jul. 2023 DST/AH/017 | Accelerometer ADC (6.25 kHz b/w) with FFT and TEDS support 12ch at 25 ksps | <ul style="list-style-type: none">• Live FFT analysis performed on each channel with the choice of viewing up to 32 of the largest peaks in the spectrum or the RMS voltage at 8 user selectable frequencies of interest• 12 single-ended, AC-coupled channels• Shared signal wire constant current excitation (3.6 mA nom.) suitable for ICP sensors• High AC accuracy (0.45% FSR typical)• Short on any channel does not affect others• 16-bit simultaneous sampling with three configurable output streams on each channel• TEDS discovery in DAS Studio 3 |
| AXN/ICP/402 21 Jul. 2023 DST/AH/016 | Accelerometer ADC (25 kHz b/w) with FFT and TEDS support 4ch at 100 ksps | <ul style="list-style-type: none">• Live FFT analysis performed on each channel with the choice of viewing up to 32 of the largest peaks in the spectrum or the RMS voltage at 8 user selectable frequencies of interest• Four single-ended, AC-coupled channels• Shared signal wire constant current excitation (3.6 mA nom.) suitable for ICP sensors• High AC accuracy (0.18% FSR typical)• Short on any channel does not affect others• 16-bit simultaneous sampling with three configurable output streams on each channel• TEDS discovery in DAS Studio 3 |

Legacy products

Since the previous bulletin, data sheets for the following products have been moved to legacy.

N/A

Obsolete documents

Since the previous bulletin, the following documents have been made obsolete.

N/A

Appendix

Reference numbers and issue dates for hardware data sheets

The following is a list of the controlled documents and their issue dates.

To ensure that you have the most up-to-date data sheet, compare your documentation against the issue date(s). To receive updated copies of any data sheets, e-mail the required list to acra-support@curtisswright.com. If you are a member of our web site, you can view and download updated data sheets from www.curtisswrightds.com.

| Product | Issue date reference number |
|---------------------------|-------------------------------|
| Axon products | |
| Axon handling precautions | 16 Dec. 2022 DST/AE/024 |
| AXN/ABM/401 | 18 Apr. 2023 DST/AC/021 |
| AXN/ADC/401 | 19 Jul. 2023 DST/AB/019 |
| AXN/ADC/404/B | 23 Jan. 2023 DST/AG/024 |
| AXN/ADC/405 | 23 Jun. 2023 DST/AE/004 |
| AXN/ADC/406 | 23 Jun. 2023 DST/AF/010 |
| AXN/ADC/408 | 3 Jan. 2023 DST/AE/003 |
| AXN/BCU/402/C | 21 Apr. 2023 DST/AH/004 |
| AXN/CHS/03U | 21 Feb. 2023 DST/AF/041 |
| AXN/CHS/06U | 21 Feb. 2023 DST/AB/031 |
| AXN/CHS/09U | 21 Feb. 2023 DST/AC/029 |
| AXN/CHS/16U | 21 Feb. 2023 DST/AB/022 |
| AXN/CHS/16U/AB2 | 19 Jun. 2023 DST/AJ/011 |
| AXN/DSI/401 | 22 May 2023 DST/AE/020 |
| AXN/DSI/402 | 29 May 2023 DST/AF/036 |
| AXN/DTU/001 | 29 Jun. 2023 DST/AH/040 |
| AXN/ENC/401 | 4 Mar. 2022 DST/AE/002 |
| AXN/ENC/402 | 28 Jul. 2022 DST/AG/005 |
| AXN/EXT/401 | 30 Sep. 2021 DST/AB/025 |
| AXN/ICP/401/B | 17 Jul. 2023 DST/AH/017 |
| AXN/ICP/402 | 21 Jul. 2023 DST/AH/016 |
| AXN/HSS/401 | 17 Feb. 2023 DST/AG/018 |
| AXN/ITE/01U | 20 Sep. 2022 DST/AB/023 |
| AXN/MBM/401 | 18 Apr. 2023 DST/AF/002 |
| AXN/MBM/402 | 11 Jun. 2021 DST/AF/003 |
| AXN/MEM/401 | 29 Jun. 2023 DST/AH/013 |
| AXN/SSD/001/256GB | 29 Jun. 2023 DST/AH/039 |
| AXN/TCG/401/B | 28 Jul. 2022 DST/AG/004 |
| AXN/TDC/401 | 9 Dec. 2022 DST/AE/005 |
| AXN/UBM/401 | 3 Feb. 2023 DST/AC/022 |

| Product | Issue date reference number |
|------------------------------|-------------------------------|
| Axon Quick Start Kit | 23 Mar. 2022 DST/AE/008 |
| CON/PSU/008 | 15 Nov. 2019 DST/AF/037 |
| Unboxing Axon QSK | 19 Oct. 2021 DST/AG/002 |
| Acra KAM-500 products | |
| 3D drawings | 10 Oct. 2019 DST/X/034 |
| ACC/HSK/001 | 9 Jun. 2016 DST/J/064 |
| ACC/TRF/002 | 2 Dec. 2022 DST/AC/020 |
| ACD/BAC/002/B | 30 Nov. 2016 DST/W/106 |
| ACD/BAC/003/B | 9 Feb. 2015 DST/W/107 |
| ACD/BAC/004/B | 9 Feb. 2015 DST/W/108 |
| ACD/BAC/005 | 9 Feb. 2015 DST/W/017 |
| ACD/BAC/006 | 25 Apr. 2023 DST/AB/003 |
| ACD/BAC/007 | 25 Apr. 2023 DST/AB/004 |
| ACD/BAC/011 | 17 Jun. 2020 DST/AG/007 |
| ACD/CJB/001 | 23 Feb. 2015 DST/P/014 |
| ACD/CJB/002 | 16 Apr. 2015 DST/W/018 |
| ACD/CJB/003 | 16 Apr. 2015 DST/Y/042 |
| ACD/CJB/005 | 5 Dec. 2016 DST/AB/001 |
| ACM/EXT/001/B | 9 Feb. 2015 DST/K/003 |
| BAC/PSU/007 | 9 Feb. 2015 DST/W/118 |
| Cables | 11 Feb. 2022 DST/J/062 |
| CON/KAD/002/CP | 8 Mar. 2022 DST/R/008 |
| CON/KAD/002/SR | 23 Jun. 2021 DST/R/009 |
| CON/KAD/003/CP | 23 Jun. 2021 DST/S/042 |
| CON/KAD/004 | 16 Apr. 2015 DST/S/040 |
| CON/KAD/005/CP | 23 Jun. 2021 DST/S/041 |
| CON/KAD/005/SR | 23 Jun. 2021 DST/T/095 |
| CON/KAD/008/CP | 2 Feb. 2022 DST/T/066 |
| CON/KAD/008/SR | 23 Jun. 2021 DST/T/067 |
| CON/KAD/010 | 23 Jun. 2021 DST/W/016 |
| CON/PSU/007 | 17 Apr. 2015 DST/W/115 |

| Product | Issue date reference number |
|----------------------|-------------------------------|
| CON/SAV/001 | 17 Apr. 2015 DST/AB/005 |
| CON/SAV/002 | 7 Apr. 2016 DST/AB/006 |
| CON/SAV/003 | 17 Apr. 2015 DST/AB/008 |
| Handling precautions | 11 May 2016 DST/U/055 |
| JIG/UNI/001/D | 28 Sep. 2021 DST/AE/019 |
| KAD/ABM/101 | 2 Sep. 2021 DST/V/064 |
| KAD/ABM/102/B | 18 May 2017 DST/Y/008 |
| KAD/ABM/102/B/EM1 | 13 Aug. 2021 DST/Y/051 |
| KAD/ABM/103 | 14 Jun. 2022 DST/X/055 |
| KAD/ADC/008 | 27 Sep. 2022 DST/N/053 |
| KAD/ADC/010/C | 17 Apr. 2015 DST/R/046 |
| KAD/ADC/011/C | 18 Mar. 2015 DST/R/044 |
| KAD/ADC/105/B | 17 Jan. 2022 DST/U/028 |
| KAD/ADC/106/C | 15 Jun. 2023 DST/U/033 |
| KAD/ADC/109/C/S1 | 19 May 2021 DST/T/097 |
| KAD/ADC/109/C/S2 | 1 Jun. 2021 DST/U/031 |
| KAD/ADC/111 | 20 Feb. 2018 DST/X/058 |
| KAD/ADC/112 | 13 Apr. 2018 DST/V/080 |
| KAD/ADC/113/B | 6 Jan. 2023 DST/V/059 |
| KAD/ADC/115 | 9 Feb. 2022 DST/Y/031 |
| KAD/ADC/116 | 25 May 2023 DST/S/083 |
| KAD/ADC/117/B | 17 Jan. 2022 DST/U/034 |
| KAD/ADC/117/EC1 | 20 Jun. 2018 DST/T/098 |
| KAD/ADC/118 | 24 Apr. 2018 DST/P/065 |
| KAD/ADC/120 | 24 Apr. 2018 DST/R/006 |
| KAD/ADC/126/B | 13 Apr. 2018 DST/V/060 |
| KAD/ADC/129/S1 | 8 May 2019 DST/S/085 |
| KAD/ADC/129/S2 | 1 Jun. 2021 DST/V/081 |
| KAD/ADC/130 | 13 Apr. 2018 DST/W/123 |
| KAD/ADC/134/B | 20 May 2021 DST/AA/014 |
| KAD/ADC/135/B | 21 May 2021 DST/AA/017 |
| KAD/ADC/136/C | 17 Dec. 2021 DST/AC/006 |
| KAD/ADC/141 | 9 Feb. 2022 DST/AC/014 |
| KAD/ARI/103/B | 23 Jan. 2023 DST/Y/044 |
| KAD/ARR/101 | 13 Apr. 2015 DST/U/047 |
| KAD/BCU/101/E | 18 Apr. 2023 DST/Y/029 |
| KAD/BCU/105/E | 27 Jan. 2016 DST/Y/034 |

| Product | Issue date reference number |
|---------------|-------------------------------|
| KAD/BCU/140/D | 18 Jan. 2022 DST/AA/037 |
| KAD/BCU/143 | 14 Apr. 2022 DST/Z/033 |
| KAD/CBM/101 | 22 Aug. 2016 DST/P/064 |
| KAD/CBM/102 | 12 Jan. 2023 DST/L/043 |
| KAD/CBM/103 | 25 Oct. 2022 DST/V/071 |
| KAD/CBM/104 | 11 Jun. 2020 DST/V/072 |
| KAD/CBM/105 | 10 Aug. 2016 DST/Y/038 |
| KAD/CBM/107 | 30 Jan. 2019 DST/Z/016 |
| KAD/CDI/101 | 14 Apr. 2022 DST/T/058 |
| KAD/DAC/001/B | 9 Nov. 2016 DST/S/050 |
| KAD/DEC/103 | 16 Sep. 2021 DST/V/074 |
| KAD/DSI/004 | 16 Feb. 2017 DST/S/105 |
| KAD/DSI/102/B | 13 Jul. 2020 DST/Y/009 |
| KAD/DSI/104 | 16 Feb. 2017 DST/W/091 |
| KAD/EBM/102/B | 4 May 2022 DST/AB/026 |
| KAD/EBM/103 | 9 Nov. 2016 DST/W/086 |
| KAD/EBM/104 | 6 Oct. 2016 DST/AB/020 |
| KAD/ENC/106 | 29 May 2020 DST/S/092 |
| KAD/ENC/111 | 22 Aug. 2016 DST/W/078 |
| KAD/ETH/101/B | 15 Aug. 2016 DST/W/128 |
| KAD/ETH/102 | 30 Jun. 2017 DST/V/073 |
| KAD/FBM/103/B | 31 Jul. 2017 DST/T/085 |
| KAD/FBM/105/B | 21 Dec. 2022 DST/AA/004 |
| KAD/IBM/101 | 2 Feb. 2021 DST/AA/005 |
| KAD/LDC/101 | 19 Oct. 2021 DST/P/048 |
| KAD/MAT/101 | 11 Apr. 2022 DST/Y/047 |
| KAD/MBM/101 | 18 Jun. 2021 DST/X/012 |
| KAD/MBM/102 | 18 Jun. 2021 DST/X/054 |
| KAD/MDC/103 | 17 Jun. 2021 DST/S/052 |
| KAD/MEM/004/B | 17 Jun. 2021 DST/T/054 |
| KAD/MSB/103/C | 8 Jun. 2021 DST/V/006 |
| KAD/PBM/104 | 30 Sep. 2016 DST/AC/013 |
| KAD/SDI/103 | 22 May 2015 DST/U/015 |
| KAD/SWI/101 | 16 Apr. 2015 DST/W/009 |
| KAD/SWI/102 | 21 Jan. 2021 DST/V/065 |
| KAD/SWI/107 | 16 Apr. 2015 DST/Y/025 |
| KAD/SWI/108 | 18 Jan. 2022 DST/Y/045 |

| Product | Issue date reference number |
|--|-------------------------------|
| KAD/TDC/002/D/10M | 22 Apr. 2022 DST/T/051 |
| KAD/TDC/102/B | 28 Feb. 2022 DST/Y/012 |
| KAD/TDC/107 | 13 Apr. 2018 DST/V/032 |
| KAD/UAR/102/C | 23 Jan. 2023 DST/X/084 |
| KAD/UBM/103 | 27 Sep. 2022 DST/Y/060 |
| KAD/UBM/106 | 26 Feb. 2020 DST/AF/038 |
| KAD/VDC/001 | 19 Jan. 2021 DST/N/065 |
| KAD/VID/106/B | 4 May 2018 DST/AB/032 |
| KAM/CDC/101 | 24 Apr. 2018 DST/S/032 |
| KAM/CHS/02F | 21 Feb. 2020 DST/X/033 |
| KAM/CHS/03F | 21 Feb. 2020 DST/P/062 |
| KAM/CHS/03U/E | 9 Jul. 2021 DST/W/042 |
| KAM/CHS/04L/B | 16 Apr. 2015 DST/N/043 |
| KAM/CHS/05F/SC | 18 Jan. 2022 DST/S/004 |
| KAM/CHS/06U/E | 9 Jul. 2021 DST/W/052 |
| KAM/CHS/09U/E | 9 Jul. 2021 DST/W/057 |
| KAM/CHS/12R/E | 12 Jan. 2016 DST/AB/027 |
| KAM/CHS/13U/E | 9 Jul. 2021 DST/W/065 |
| KAM/DMY/001 | 9 Feb. 2015 DST/U/002 |
| KAM/MEM/113 | 26 Oct. 2022 DST/X/067 |
| KAM/PSU/011/B | 16 Apr. 2015 DST/Z/021 |
| KAM/PSU/012/B | 9 Jan. 2023 DST/W/043 |
| KAM/PSU/014 | 16 Apr. 2015 DST/Y/024 |
| KAM/TCG/105 | 14 Jul. 2023 DST/Z/025 |
| KAM/TCG/106 | 18 Jul. 2023 DST/AG/014 |
| KAM/WSI/104/C | 20 Sep. 2022 DST/AC/034 |
| KIT/001 | 22 Jun. 2021 DST/J/063 |
| LID/001 | 23 Feb. 2015 DST/J/061 |
| SAM/DEC/008 | 19 Apr. 2016 DST/Z/010 |
| Wireless data acquisition evaluation kit | 19 Aug. 2021 DST/AC/011 |
| Unboxing wireless data acquisition kit | 16 Mar. 2023 DST/AH/020 |
| Ground station products | |
| Ground station cables | 3 Mar. 2015 DST/V/047 |
| GTS/BAY/001 | 3 Mar. 2015 DST/W/024 |
| GTS/BSC/003/C | 4 Apr. 2019 DST/W/134 |

| Product | Issue date reference number |
|------------------------------------|-------------------------------|
| GTS/BSC/004/C | 4 Apr. 2019 DST/W/131 |
| GTS/BSC/005/C | 4 Apr. 2019 DST/W/135 |
| GTS/BSC/006/C | 4 Apr. 2019 DST/Y/048 |
| GTS/DEC/003/C | 8 Aug. 2023 DST/W/132 |
| GTS/DEC/004/C | 8 Aug. 2023 DST/W/110 |
| GTS/DEC/005/C | 8 Aug. 2023 DST/W/133 |
| GTS/DEC/006/C | 8 Aug. 2023 DST/Y/040 |
| GTS/FSC/003/C | 4 Apr. 2019 DST/W/136 |
| GTS/FSC/005/C | 4 Apr. 2019 DST/W/137 |
| GTS/DPC/005 | 11 Mar. 2015 DST/Y/005 |
| GTS/LCD/001 | 27 Mar. 2015 DST/T/026 |
| GTS/MCI/001/C | 27 Mar. 2015 DST/Z/009 |
| GTS/NPC/001/G | 27 Mar. 2015 DST/V/051 |
| GTS/NPC/003/D | 11 Mar. 2015 DST/AA/008 |
| GTS/RCV/001 | 27 Mar. 2015 DST/T/031 |
| Recorder products | |
| CompactFlash cards | 18 Apr. 2023 DST/Y/032 |
| NET/REC/001 | 14 Feb. 2022 DST/U/039 |
| NET/REC/002 | 2 Dec. 2022 DST/V/044 |
| NET/REC/006/B | 11 Aug. 2022 DST/Y/015 |
| Solid State Drives | 20 Jul. 2021 DST/Y/033 |
| SSR/CHS/001/D | 20 Jun. 2023 DST/AE/022 |
| Network switch products | |
| ACC/KIT/005 | 20 Mar. 2015 DST/W/034 |
| BAC/MMO/001/F10 | 23 May 2016 DST/W/116 |
| BAC/MMO/001/F19 | 20 Mar. 2015 DST/W/117 |
| CON/MMO/001/F10A | 20 Mar. 2015 DST/W/113 |
| CON/MMO/001/F19A | 20 Mar. 2015 DST/W/114 |
| Network Cables | 3 Jun. 2021 DST/W/022 |
| NET/SWI/001 | 16 Jan. 2018 DST/U/040 |
| NET/SWI/006 | 18 Jan. 2021 DST/V/049 |
| NET/SWI/101/B | 15 May 2023 DST/AA/015 |
| NET/SWI/101/C | 23 Jun. 2023 DST/AC/004 |
| System integration products | |
| RFE/AEG/001 | 5 May 2023 DST/S/033 |

| Product | Issue date reference number |
|--------------------------|-------------------------------|
| Avionics products | |
| OBE/CAM/001 | 4 Dec. 2019 DST/AB/010 |
| OBE/CAM/002 | 4 Mar. 2016 DST/AA/011 |

DAS Studio 3 software known issues

Modules supported in this release

See “Products supported by DAS Studio 3” on page 24.

New features added in this release

| Feature description |
|---|
| Parameter search tool improvements including filtering and copy |
| Data Exporter command line tool |
| New column in Parameters Palette showing parameters already placed in other Ethernet packages |
| New Properties icon in transmission assistant |
| Package Generator no longer runs for PCM modules |

Known issues in this release

| Issue # | Project | Description |
|---------|-------------------------------|---|
| AFDX-1 | Studio ARINC-NDO Importer | Parameter naming clash reported after a successful ARINC-NDO import of AFDX parameters |
| ALG-6 | Studio Algorithms Tab General | The Error message (x) stays on algorithm tab even after removing the 'trigger condition' |
| ALG-11 | Studio Algorithms Tab General | Only a single window for the values to cause an event is available for the BIT101 or BIT102 in Das Studio meaning you can check an internal range, but cannot check an external range |
| APP-56 | Studio Applications General | Unable to load DLL 'gtsdecw.dll': The specified module could not be found. (Exception from HRESULT: 0x8007007E) |
| ARINC-9 | Studio ARINC-429 Builder | When changes are made to the SDI or SSM values, Save and Close button only becomes active after the table has lost focus |
| CBW-9 | CAN-Bus Builder | CAN Builder of DAS Studio - Extended ID shows incorrect filtering |
| CFT-68 | Calibration Fetch | Calibration Fetcher seems to be confused for modules on a slave |
| CFT-76 | Calibration Fetch | Calibration Fetcher - Index was outside the bounds of the array. |
| DAS-318 | DAS Studio General | Changing Windows theme while DAS Studio is running may cause DAS studio to become unstable |
| DAS-396 | DAS Studio General | Old Tasks may appear invalid due to changes in xDefML files |
| DAS-433 | DAS Studio General | It is necessary to run DAS Studio as administrator on Windows 7 OS |
| DAS-472 | DAS Studio General | DAS Studio GUI appears to be doing nothing during Program or Verify while Multi-Chassis Scheduler is running |
| DAS-591 | DAS Studio General | Multi Chassis Scheduler does not automatically transfer parameters from a slave chassis to a BIT102 module for event monitoring |
| DAS-616 | DAS Studio General | Palette caches imported files but does not reuse them resulting in poor memory performance |
| DAS-716 | DAS Studio General | GUI allows users to add parameters to Parser aligned iNET-X Packages, resulting in invalid XidML files |
| DAS-734 | DAS Studio General | If the installation path name changes with new versions of DAS Studio, references to lookup files may become invalid in old tasks and require updating |
| DAS-740 | DAS Studio General | Message server displays Compilation Complete after programming hardware |

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-747 | DAS Studio General | DAS Studio does not automatically calculate and update the PCM Major Frame Rate |
| DAS-906 | DAS Studio General | Under rare circumstances the vertical scroll bar may disappear on the global parameter list and does not return until you restart DAS Studio |
| DAS-1019 | DAS Studio General | Calibration Fetcher does not discover slave DAU |
| DAS-1033 | DAS Studio General | DAS Studio is stuck in update loop when attempting to add parameters to packet. |
| DAS-1065 | DAS Studio General | DAS Studio crashes if a second instance is opened |
| DAS-1075 | DAS Studio General | DSI102 Size in Bits settings of the counter size is missing in DAS Studio: Parameter size for DSI102 family modules Counters is available in 16 bits and 32 bits resolutions. Other bit size can be changed on the parameter list |
| DAS-1107 | DAS Studio General | DAS Studio may become unstable if "&" is used in a packet name. |
| DAS-1133 | DAS Studio General | Delay added to the PCM frame in Ethernet to PCM systems may be large under certain configurations |
| DAS-1160 | DAS Studio General | GUI may jump focus when switching between tabs |
| DAS-1163 | DAS Studio General | When manually defining parameters for parser packages the full list of parameters available is shown |
| DAS-1164 | DAS Studio General | Cannot uses "/" in #define statements for MAT101 Header files |
| DAS-1167 | DAS Studio General | MEM103 Package builder shows blank values for parameter already placed in the MEM103 due to different default base sampling rate |
| DAS-1180 | DAS Studio General | ARINC-429 builder hangs when closing it from the X in the top right of its window |
| DAS-1189 | DAS Studio General | DAS Studio Packages Tab PCM builder crashes when changing parameters manually |
| DAS-1191 | DAS Studio General | DAS Studio does not warn user if a process is not linked to a package |
| DAS-1199 | DAS Studio General | GUI for the ADC013 Modules Settings allows user to set Range Max to be less than Range Min. the user will not be warned in the GUI, but will receive an error message at compile time |
| DAS-1204 | DAS Studio General | Filtering not Activated by hitting return |
| DAS-1215 | DAS Studio General | Hardware programming time increase |
| DAS-1221 | DAS Studio General | IP addresses are going missing in packages |
| DAS-1241 | DAS Studio General | Synchronous connection is assumed for PCM links |
| DAS-1251 | DAS Studio General | Packet-Filter on EBM102 should not use the same IP as other packets in the task. May result in compilation errors |
| DAS-1262 | DAS Studio General | Package Generator does not warn it will delete/modify existing packets |
| DAS-1283 | DAS Studio General | DAS Studio show an error 'The directory is not empty' when the cache directory is open by windows explorer |
| DAS-1309 | DAS Studio General | A configuration can be verified but issues no packets from DAU 3 |
| DAS-1315 | DAS Studio General | TCG103 from DAS Studio 3.2 fails to open in DAS Studio 3.4.0 due to changes in the xDefML file |
| DAS-1353 | DAS Studio General | If Scheduling cannot be achieved, you may see 'Unexpected late transfer' error |
| DAS-1360 | DAS Studio General | When X_SYNC is enabled on the TCG modules the compiler does not check to see if the acquisition cycle is valid |
| DAS-1370 | DAS Studio General | FBM102 is not a standard FireWire module. Packages and parameters must be added from the Packages tab and not the FireWire builder. A specific FBM102 firewire package can be added from the palette. When using the wizard, users should ignore the FBM102. |
| DAS-1418 | DAS Studio General | To manually place a parameter using 1:1 commutation in the Transmission Assistant you must Drag and drop to the first minor frame |

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-1419 | DAS Studio General | Burst Placement of video parameters may take some time to complete in large PCM frames |
| DAS-1436 | DAS Studio General | DAS Studio may be slow to respond after compilation / Programming, user will not be asked to 'Please wait' |
| DAS-1439 | DAS Studio General | Burst Placement may fail if Smart placement is enabled |
| DAS-1442 | DAS Studio General | Filtering on PCM Parameter grid may still be applied from previous task settings |
| DAS-1450 | DAS Studio General | Smart mode will not use the last word on the PCM |
| DAS-1459 | DAS Studio General | In the PCM Package grid the full Parameter name may not be displayed |
| DAS-1460 | DAS Studio General | Error Message 'Tried to access to an unavailable frame location', when placing 8 parameters at 1:2 using smart mode in frame with enough space to place all commutations |
| DAS-1462 | DAS Studio General | In the Transmission Assistant, when Smart Placement mode is enabled the Parameter place parameters vertically or horizontally setting is ignored |
| DAS-1464 | DAS Studio General | Crash when clicking on PCM frame too often |
| DAS-1479 | DAS Studio General | Palette with add with connections in PCM will only import the frame shape |
| DAS-1498 | DAS Studio General | Adding a hex alpha character to an integer field in a generic package setting causes DAS Studio to crash |
| DAS-1536 | DAS Studio General | Standalone compiler crash (access denied) on launch when DAS Studio is running on Windows 7 32-bit OS |
| DAS-1564 | DAS Studio General | VID106 or 103 in 2 different packages must have the same sampling rate |
| DAS-1575 | DAS Studio General | Video cannot be transmitted over ETH and over PCM simultaneously |
| DAS-1583 | DAS Studio General | Video burst in MCS for PCM fails compiling |
| DAS-1585 | DAS Studio General | Failure in PCM_WD_SETUP after adding burst video |
| DAS-1587 | DAS Studio General | Crash when del parameter MyARINC-429-WordPackage from global parameter list |
| DAS-1609 | DAS Studio General | Parameter name should not contain dots otherwise they cannot be opened by Matlab |
| DAS-1614 | DAS Studio General | When parameters are placed into the PCM, users should not be allowed to change sampling rate |
| DAS-1615 | DAS Studio General | Changing rate on multiple parameters is only possible if the mouse is still on the selected area |
| DAS-1621 | DAS Studio General | No decimation on analog modules should create an error |
| DAS-1632 | DAS Studio General | MCS packets should not be created |
| DAS-1635 | DAS Studio General | DEC103 is limited to 8Mbits in synchronous mode but DAS Studio compiles successfully |
| DAS-1638 | DAS Studio General | Quite slow to add few parameters into a PCM with some parameters already placed |
| DAS-1639 | DAS Studio General | MCS does not need to transmit the transport package at the same rate as a secondary PCM transmitter package in a slave chassis. |
| DAS-1642 | DAS Studio General | Wrong link appears to be renamed when renaming is done with the 'F2' short cut after renaming with the context menu |
| DAS-1647 | DAS Studio General | Scheduling Error : Failed to generate timing window for ANE2[15:0](0)<(Parser9:36)[15:0]-s(7+7)/56 |
| DAS-1666 | DAS Studio General | DAS Studio - The value 'OffsetBinary' is not valid - BitVector is the only allowed value |
| DAS-1667 | DAS Studio General | No access for BIT101_SINK is 1 but must be 2 |
| DAS-1731 | DAS Studio General | DS1102 should not compile on the attached setting |
| DAS-1738 | DAS Studio General | Ethernet to PCM bridge does not work until you save and reopen the file |
| DAS-1748 | DAS Studio General | Recorder Status Tool in DAS Studio does not report errors connecting to recorders |

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-1771 | DAS Studio General | NETREC006 and SSR/CHS SNMP variables are programmed correctly but the hardware fails to transmit the correct value back to software. |
| DAS-1772 | DAS Studio General | Default Stream ID of FFFFFFFF is the same value as SSR/CHS/001/B default filter, hence packets with that stream ID will not be transmitted, unless filter is changed. |
| DAS-1774 | DAS Studio General | Documentation link does not work for certain modules |
| DAS-1794 | DAS Studio General | Discovery tool should state "no hardware found" on Studio |
| DAS-1795 | DAS Studio General | System.InvalidOperationException when clicking on GS Status |
| DAS-1812 | DAS Studio General | BSC003C: gStatus should not display "DecomeLock(0)" |
| DAS-1813 | DAS Studio General | Studio allows user to run on gStatus while another gStatus is running but doesn't display any LED definition for the second gStatus. |
| DAS-1821 | DAS Studio General | Programming cannot be cancelled |
| DAS-1841 | DAS Studio General | Transmission assistant corrupts the PCM frame |
| DAS-1852 | DAS Studio General | KAMCSB12U Discovers incorrectly in DAS Studio 3.4.1 |
| DAS-1855 | DAS Studio General | After a calibration error occurs during programming from DAS Studio, the message box appears after the end of the operation to inform the user that the system programmed successfully when it did not |
| DAS-1865 | DAS Studio General | IP Programmer reports a false Fail message |
| DAS-1880 | DAS Studio General | Bridge balancer adds fields to the XIDML not included in XDEFML |
| DAS-1890 | DAS Studio General | "56ia is not a valid integer value" error message when installing and launching DAS Studio/msgsvr.exe |
| DAS-1892 | DAS Studio General | EBM with 3rd party Ethernet and MCS do not work |
| DAS-1916 | DAS Studio General | Attempting to elevate any sub-parameter on a 16-bit boundary to a payload parameter without introducing overlaps. |
| DAS-1917 | DAS Studio General | Package import , parameter no longer sourced from user module but from controller |
| DAS-1923 | DAS Studio General | Parsing MCS and Generic in the EBM is not intuitive |
| DAS-1968 | DAS Studio General | EBM104 not coherent on parameter name |
| DAS-1971 | DAS Studio General | ALL the EBM104 parameters to be removed from the iNET-X /PCM packets after an import |
| DAS-2010 | DAS Studio General | Calibration files are not stored under the C:\ProgramData\ACRA anymore |
| DAS-2057 | DAS Studio General | Error compiling doesn't help finding where the issue is ..."Value was either too large or too small for a UInt32" |
| DAS-2064 | DAS Studio General | Datasheet: DAS Studio does not support discrete output setup on KADDAC001 |
| DAS-2104 | DAS Studio General | CVSD created by DAS Studio do not match the TEC-NOT-067 |
| DAS-2132 | DAS Studio General | Quicklook fails to open, giving error with no detail due to path issue. Quicklook cannot find SAMDEC dll as current working directory has changed |
| DAS-2143 | DAS Studio General | Valid UAR parsed data only starts at data word offset 2 onwards |
| DAS-2163 | DAS Studio General | Coma's localization cause programming error with a NETSW101C |
| DAS-2169 | DAS Studio General | Attached are some app/tool cases of font not changing when font option is change under options |
| DAS-2185 | DAS Studio General | SWP_SDK_004 is missing in DAS Studio installer |
| DAS-2208 | DAS Studio General | leading 0s for hexadecimal start and stop pattern are removed by serial builder |
| DAS-2232 | DAS Studio General | For KAMFBM001B and KAMFBM001 the numeric base of the FCS input is not clear |

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-2262 | DAS Studio General | Failed to create parser parameter P_MyKAD_EBM_102_B_Report: There is no parser slot allocated for the Package MyPlacediNET-XPackage |
| DAS-2272 | DAS Studio General | After running Bridge Balancer, DAS Studio crashes when ADC136 input type is changed |
| DAS-2294 | DAS Studio General | A xidml file with a PCM package does not show up in das studio when modes are enabled |
| DAS-2295 | DAS Studio General | Smart placement fails to place parameters that fit in the PCM frame |
| DAS-2301 | DAS Studio General | DAS Studio for ENC-106 in mode select saves a file with FrameFormatIdentifier overlapping a parameter |
| DAS-2307 | DAS Studio General | 97012 Warning: Late transfer at tick 1840 with lateness 2. PAR_TS1[15:0](0)<MPEG2TS[15:0]-s(30+1)/610 |
| DAS-2312 | DAS Studio General | Huge offset of about 1000 counts on ADC116 modules due to calibration confusion |
| DAS-2332 | DAS Studio General | Very long save for ethernet builder and PCM frame after editing |
| DAS-2351 | DAS Studio General | Package Generator shows up empty when opened from the tool's menu for the first time |
| DAS-2360 | DAS Studio General | French and German language localization causes problem related of calibration fetcher |
| DAS-2389 | DAS Studio General | Warning. Default Calibration Data used for module KAM/CDC/101 |
| DAS-2423 | DAS Studio General | VID103 timer doesn't work |
| DAS-2447 | DAS Studio General | Serial Number synchronizer fails on a ETH101 system |
| DAS-2552 | DAS Studio General | ARINC429 builder the default label format is octal, but the "default" is instead associated to the decimal |
| DAS-2571 | DAS Studio General | Compiler does not report an error when MCS turned off. BCU resets |
| DAS-2629 | DAS Studio General | Status Stream Identifier is for IENA Key too |
| DAS-2632 | DAS Studio General | A configuration with a DEC003 in asynchronous mode shows spikes |
| DAS-2633 | DAS Studio General | Scheduling Error: Estimated ticks 12447892 needed to schedule 6223946 transfers is too much to fit in 1000000 ticks due to localization issue |
| DAS-2638 | DAS Studio General | AXNABM401 Arinc Builder should not compile when label has exceeded 377 |
| DAS-2693 | DAS Studio General | EBM102 process prevents from creating generic parser flow |
| DAS-2703 | DAS Studio General | LoTime sometimes is described as BCD and sometimes as BitVector |
| DAS-2803 | DAS Studio General | IP address programmer localization issue when assigning IP to a NETSWI101 |
| DAS-2819 | DAS Studio General | AXN/TDC/401 when uses built-in temperature sensors for cold junction compensation, will be -2C deg off expected value on thermocouple channels |
| DAS-2846 | DAS Studio General | Exception Invalid XidMLFile:14zo2nbd.sge , Inner Exception System.ArgumentNullException: La valeur ne peut pas être null |
| DAS-2854 | DAS Studio General | Message server log is not showing correct SNMP OID Setting |
| DAS-2880 | DAS Studio General | Scheduling Error : Failed to generate timing window for |
| DAS-2881 | DAS Studio General | Transmission assistant should start on the first available minorframe when vertical placement |
| DAS-2895 | DAS Studio General | DAS Studio noncritical compiler backplane timings warning should be hidden from the log and available as a debug option only |
| DAS-2909 | DAS Studio General | importing 1553 message requires the parameter section |
| DAS-2939 | DAS Studio General | Loss of focus on PCM map |
| DAS-3010 | DAS Studio General | should have not compiled due to the minimum transmit time |
| DAS-3045 | DAS Studio General | Cannot discover when chassis ID is 1 |

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-3050 | DAS Studio General | cfgcnt file created when programming configuration |
| DAS-3084 | DAS Studio General | MCS modifies the sub-parameters into a parameter |
| DAS-3105 | DAS Studio General | XIDML file with ghost parameters without any instrument or source generated after splitting registers |
| DAS-3107 | DAS Studio General | DAS Studio hangs when multiple parameters with a size inferior to 16 bits are added into an ethernet packet |
| DAS-3108 | DAS Studio General | DAS Studio overlaps the parameters when a size superior to 16 bits is added into an ethernet packet |
| DAS-3110 | DAS Studio General | AXNADC401 MIN-MAX is not saved properly in the xidML file |
| DAS-3148 | DAS Studio General | BCU101 mixed with BCU105 should not compiled |
| DAS-3154 | DAS Studio General | Could not establish or maintain reliable connection with the hardware at IP-address |
| DAS-3167 | DAS Studio General | should place all possible parameters if an error occurs |
| DAS-3189 | DAS Studio General | AXN ABM 401 parameter names are different depending on the controller in the chassis |
| DAS-3288 | DAS Studio General | Transmission assistant: You cannot unset a rate |
| DAS-3289 | DAS Studio General | Transmission assistant: if parameter gets "cannot place", even though you have room, you will never be able to place it |
| DAS-3296 | DAS Studio General | cannot program existing chassis |
| DAS-3319 | DAS Studio General | Empty serial number does not produce a warning or an error in DAS studio |
| DAS-3343 | DAS Studio General | Read counter parameter is missing when AXNBCU401 is discovered |
| DAS-3344 | DAS Studio General | Discovered Module 0x593 in slot number J7 in chassis 10.143.9.30 does not exist in cache. Module will not be programmed |
| DAS-3349 | DAS Studio General | AXNBCU401 with IENA pkt fails to verify |
| DAS-3350 | DAS Studio General | Removing an ENC401 from the chassis causes DAS studio to crash |
| DAS-3383 | DAS Studio General | Not all Fs are powers of 2 from the base Fs on module MyAXN_ADC_401 |
| DAS-3401 | DAS Studio General | NET-SWI-101 - when setting a multicast address to a status packet the MAC address is not updated accordingly |
| DAS-3402 | DAS Studio General | Datasheet needs to be updated - MSB-103-C should not show bus ID with values 0 to 7 |
| DAS-3406 | DAS Studio General | DAS Studio should enforce Only one MEM-x0x can be installed in an Acra KAM-500 chassis. |
| DAS-3415 | DAS Studio General | NET-SWI-101-C filtering GUI crashes when using a nonstandard character (by mistake) |
| DAS-3422 | DAS Studio General | MEM-113 should be able to log its own register MEM-113 status STATUS and ERROR_COUNT |
| DAS-3429 | DAS Studio General | KAD/BCU/140/CH10 from DAS Studio palette is not a supported module and should not show up |
| DAS-3473 | DAS Studio General | Fixed data is expected to change according to the Shunt mode value |
| DAS-3503 | DAS Studio General | parser tags are not functioning on the UAR102B |
| DAS-3506 | DAS Studio General | Datasheet link disappears after programming |
| DAS-3507 | DAS Studio General | very slow to delete parameters from the serial builder |
| DAS-3511 | DAS Studio General | SSR/CHS/001/D: "System.NotSupportedException: Unsupported value 'False' for constraint type 'System.Boolean' on setting 'PTPv1 Disable BMCA'" - way around set the setting to True on the xidML file |
| DAS-3603 | DAS Studio General | AXNABM401 creates packetizer at 1Hz instead of a min of 39Hz |

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-3605 | DAS Studio General | Smart Placement Mode for PCM frame fails when burst placement used |
| DAS-3606 | DAS Studio General | Error from MCS: Cannot fit parameter XYZ into the transport packet |
| DAS-3623 | DAS Studio General | Serial Number Synchronizer crashes with attached XidML when Reading Hardware |
| DAS-3631 | DAS Studio General | Slave is not discovered over ETH102 |
| DAS-3663 | DAS Studio General | MCS Error - Video burst transport fails to compile |
| DAS-3674 | DAS Studio General | EBM104 dataset size change makes changes on the parameter name |
| DAS-3682 | DAS Studio General | No video with burst placement |
| DAS-3689 | DAS Studio General | The given value of type String from the data source cannot be converted to type nvarchar of the specified target column |
| DAS-3690 | DAS Studio General | Commutation is not correct when a burst parameter is placed |
| DAS-3721 | DAS Studio General | Slave is not programmed if master chassis is missing using a SAMDEC008 |
| DAS-3725 | DAS Studio General | Video not present in PCM when the video is transported by a remote chassis |
| DAS-3731 | DAS Studio General | System.Xml.XmlException: "" is an unexpected token. |
| DAS-3743 | DAS Studio General | Error is not clear: The given key was not present in the dictionary |
| DAS-3749 | DAS Studio General | should not allow the user to change the UDP header transfer format |
| DAS-3752 | DAS Studio General | App Builders: Word offset Increment is acting strangely |
| DAS-3777 | DAS Studio General | Serial Builder: parameter name edit not user friendly |
| DAS-3778 | DAS Studio General | Serial package - cannot edit package name in specific cases |
| DAS-3779 | DAS Studio General | Failed to generate for module KAD/ENC/106 - Mode conflict found at PCM MyIRIG-106-Ch-4Package_4_256x16 - mode is 'False' but FrameFormatIdentifier is not empty |
| DAS-3780 | DAS Studio General | Enabling mode makes the PCM not visible |
| DAS-3786 | DAS Studio General | spaces in package name creates verification error |
| DAS-3789 | DAS Studio General | Renaming Connections on SWI not updating |
| DAS-3794 | DAS Studio General | PCM justification left right not supported |
| DAS-3795 | DAS Studio General | RangeScale_Excitation_Linearization_ADC113 error |
| DAS-3803 | DAS Studio General | DSI102 and DSI102B Xdefml files are reversed for event parameter description |
| DAS-3805 | DAS Studio General | Windows update KB4578968 creates refresh issues |
| DAS-3812 | DAS Studio General | Multiple selection and renaming of parameters in the Placed Data window of the Packages Tab does not follow a logical renaming sequence |
| DAS-3841 | DAS Studio General | Adding parser slot to UBM/401 corrupts xidml |
| DAS-3858 | DAS Studio General | Naming of functionalities in bus packetizer modules |
| DAS-3875 | DAS Studio General | programming error has a confusing slot |
| DAS-3876 | DAS Studio General | NETSWI101 in PTP Transparent Switch should create an error if the ports do not use the same PTP version |
| DAS-3878 | DAS Studio General | Ethernet transmitter 'MySSR_CHS_001_D' can handle less than 1048576 transfers but 1503162 requested - problem is setup only contains Packetizer packets - way around create a place packet to force an acquisition cycle |
| DAS-3900 | DAS Studio General | Multiset and edit are inconsistent |
| DAS-3933 | DAS Studio General | AXNBCU402 connected directly to a KADBCU140 shows only packets from the KADBCU140 |

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-3941 | DAS Studio General | ENC005B - parameter in 12 bits fixed word PCM is not correct |
| DAS-3949 | DAS Studio General | AXNENC401 generic parsing: Not Used is the only allowed value |
| DAS-3959 | DAS Studio General | removing chassis doesn't remove the modules |
| DAS-3974 | DAS Studio General | Discrete parameters can be added over Ethernet |
| DAS-3978 | DAS Studio General | cannot open xidML file System.ArgumentNullException: Value cannot be null. Parameter name: name |
| DAS-3984 | DAS Studio General | hover tip only shows for the initial connection |
| DAS-3993 | DAS Studio General | PCM frame drops |
| DAS-4006 | DAS Studio General | Specific PCM shape should be allowed |
| DAS-4017 | DAS Studio General | Compile error: BalanceTarget for channel 0 in volts is 2.50 for ADC406 doesn't make sense |
| DAS-4032 | DAS Studio General | Adding a Package to KADFBM105B shows drop down settings for PT-Packet and LLP |
| DAS-4040 | DAS Studio General | Custom control validation error expected 'Current' but found 'Voltage' on setting 'Excitation Mode' when setting 'Input Mode' is 'ICP sensor' |
| DAS-4084 | DAS Studio General | Calibration fetcher fetching from un-calibrated ADC/116 |
| DAS-4090 | DAS Studio General | file: added in the MDC103 path suffix |
| DAS-4124 | DAS Studio General | xDefML for the KADSWI108 has conditions which do not make sense for the port settings |
| DAS-4151 | DAS Studio General | AXNADC405 differential ended configuration, with signal source isolated from module ground (pull-down resistor on the module enabled) |
| DAS-4153 | DAS Studio General | AXNENC402 frame is cleared after a change in the Ethernet builder |
| DAS-4206 | DAS Studio General | remove orphan parameter doesn't work for tags parameter |
| DAS-4209 | DAS Studio General | After discovering a NETSWI101C, all the modes for each port map to other ports are shown |
| DAS-4226 | DAS Studio General | Adding ETH report word to its own packet should give a compile error |
| DAS-4251 | DAS Studio General | Compilation error doesn't tell you the exact module for which it happens |
| DAS-4256 | DAS Studio General | KADENC106 and KADBCU101 Major Pulse currently not supported by DAS Studio |
| DAS-4266 | DAS Studio General | ENC402 Ch7 length in Bytes error is not correct |
| DAS-4270 | DAS Studio General | Hdefml file missing error when running discovery on AXNBCU401 module |
| DAS-4271 | DAS Studio General | AXNENC402 Error in DAS Studio about Ch7 PTFR length while the setup compiles with no errors |
| DAS-4282 | DAS Studio General | DECx03 should allow 0x0123 as a syncword |
| DAS-4305 | DAS Studio General | DAS Studio shouldn't crash if the parameters are referenced but not defined |
| DAS-4306 | DAS Studio General | Do not ask you to save before verifying/programming if your xidml file got modified and not saved |
| DAS-4322 | DAS Studio General | Refresh issue on packages tab when SBM101 setting EFEX / STANAG are changed. User needs to click on another module and then back for change to update |
| DAS-4323 | DAS Studio General | slave is not discovered using a ETH101 |
| DAS-4360 | DAS Studio General | spaces in the DAS Studio install path causes Scheduling Error: Already ReportedACRA.Common.Helpers.ReportedException: Already Reported ---> System.IO.FileNotFoundException |
| DAS-4381 | DAS Studio General | Lookup file should be able to load into the linearization URL field |
| DAS-4391 | DAS Studio General | Windows 10 launch issue. WaitForInputIdle failed. This could be because the process does not have a graphical interface. |

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-4397 | DAS Studio General | EXC101 limits are wrong |
| DAS-4398 | DAS Studio General | Modifying the destination IP on the package viewer makes the view to jump to the first packet and on the left |
| DAS-4399 | DAS Studio General | DSI104-5V should not be in the module palette |
| DAS-4441 | DAS Studio General | MEM113 storage time/BCU ethernet output rate - Not implemented for Packetizers. |
| DAS-4467 | DAS Studio General | Bad data coming out of an ENC106 that verifies successfully - potentially due to CVT reuse |
| DAS-4489 | DAS Studio General | slow when you click on the BCU140 link to display packets |
| DAS-4499 | DAS Studio General | Save As xidML does not retain the parameter information from the transmission assistant |
| DAS-4533 | DAS Studio General | BCU101C is not showing video from VID106 |
| DAS-4536 | DAS Studio General | Not enough space to place parameters into MEM package |
| DAS-4580 | DAS Studio General | Minor updates required in the Installation guide. |
| DAS-4588 | DAS Studio General | DAS Studio hangs when attempting to relocate parameters in package content payload |
| DAS-4597 | DAS Studio General | AXNENC40x: Ethernet builder should limit the number of frames according to the parser buffer depth - the number parser slots and parser buffer depth are related |
| DAS-4598 | DAS Studio General | Deleting parameters causes jump to first defined packet on removal |
| DAS-4603 | DAS Studio General | ACRA.FtiDomainRepositoryBuilder.InvalidXidMLFileException: Sub Parameter - this error points to a incorrectly formed XIDML file |
| DAS-4613 | DAS Studio General | Cannot discover SSRREC001 |
| DAS-4623 | DAS Studio General | TAG parameters TAB not available in Ethernet builder if a Switch with import port also in project |
| DAS-4649 | DAS Studio General | Warning: Late transfer at tick xx with lateness yy - in some scenarios this should an error - delaying PCM might solve the warning |
| DAS-4662 | DAS Studio General | install path cannot be selected anymore |
| DAS-4665 | DAS Studio General | Modifying the occurrences in the Placed Data tab will not change the rate in the transmission assistant |
| DAS-4668 | DAS Studio General | BB: log should have an option to output more info |
| DAS-4687 | DAS Studio General | DAS Studio shut down (crashes) when try to remove the Async PCM in the DEC103 |
| DAS-4703 | DAS Studio General | DAC001 cannot use MCS |
| DAS-4709 | DAS Studio General | changing syncword in PCM will make DAS Studio crash |
| DAS-4722 | DAS Studio General | xReport Application crash |
| DAS-4729 | DAS Studio General | StandaloneCompiler reports "programming completed with errors" but there's no errors in the log |
| DAS-4730 | DAS Studio General | Renaming a filter rule doesn't rename where it is used |
| DAS-4733 | DAS Studio General | xidML version not updated |
| DAS-4736 | DAS Studio General | Import one message only on a Serial Bus monitor channel |
| DAS-4737 | DAS Studio General | importing twice a CSV to a serial module will not import the parameters on the second time |
| DAS-4739 | DAS Studio General | CSV exported doesn't output correctly the extended ID |
| DAS-4740 | DAS Studio General | EBM: when VLAN is enabled, we should set a warning dialog |
| DAS-4744 | DAS Studio General | KAD/BCU/140/DEM not supported by IP Address Programmer |
| DAS-4748 | DAS Studio General | "Can't find source for parameter" on an Axon chassis connected to a KAM-500 |

| Issue # | Project | Description |
|----------|-----------------------------|---|
| DAS-4750 | DAS Studio General | add NSW-SWI-012 hDefml and xDefML in DAS Studio installer |
| DAS-4751 | DAS Studio General | Axon and KAM500 hybrid system is not coherent |
| FAL-330 | Falcon (EEPROM Generator) | Sample rate of Ethernet PCM Bridge parameters are driven by Ethernet not PCM when sub parameters are placed in PCM |
| FAL-331 | Falcon (EEPROM Generator) | No output from ADC-136 when erasing MEM-113 in format 8 or idle in format 4 |
| FOP-62 | Studio File Operations | Error message for dynamic constraint generation does not specify the setting / channel / instrument the error is on |
| MCS-1 | Multi Chassis Scheduler | Users will see an error when compiling or programming a task if they have manually built a slave PCM frame. |
| MCS-136 | Multi Chassis Scheduler | Having multiple PCM package in a task while Packetization enabled on single ENC106 channel cause an error |
| MCS-201 | Multi Chassis Scheduler | Packetizer for ABM103 Schedules same number of packets per second regardless of the Bus speed setting |
| MCS-209 | Multi Chassis Scheduler | Error '...not present in dictionary' after replacing slave PCM on detection of previous package |
| MCS-228 | Multi Chassis Scheduler | Multi Chassis scheduler - Project with VID-106-B in remote computer creates incorrect packets |
| MCS-230 | Multi Chassis Scheduler | DAS Studio create a link appending "_packetizing" when running the MCS even when there is no package attached. |
| MIL-5 | Studio MIL-STD-1553 Builder | More data word parameters can be added than defined in the message Parsing Rules |
| MSI-109 | Studio Installer | DAS Studio installer may cause anti-virus software to issue a warning |
| MSI-149 | Studio Installer | DAS Studio installer may remove components that affect KSM-500 and kFlashCard when uninstalling |
| MSI-167 | Studio Installer | 'UnauthorizedAccessException' error on Windows XP when tried to run DAS Studio as limited user, although it was installed as admin user |
| MSI-190 | Studio Installer | User may see an Error message when installing if user doesn't have Admin rights |
| MSI-254 | Studio Installer | Uninstalling DAS Studio deletes the calibration information gathered by Calibration Fetcher |
| MSI-283 | Studio Installer | .NET 4.0 Framework will not install if the Windows Imaging Component is not already installed |
| MSI-316 | Studio Installer | SWP-SDK-004 (SAMDEC008 driver) missing from the installation |
| PB-48 | Studio Package Builder | Package builder displays 'Package generation complete' even if no packages are created |
| PB-57 | Studio Package Builder | Using an illegal bit rate in the PCM package generator may cause it to hang, the Transmission Assistant should be used instead |
| PB-71 | Studio Package Builder | Encountering Errors in PCM package generator may result in an empty PCM frame. Transmission Assistant should be used instead |
| PB-72 | Studio Package Builder | Package Builder should not alter an existing PCM frame that already works |
| PB-74 | Studio Package Builder | Package builder does not remember if you locked a parameter to a PCM location |
| PB-76 | Studio Package Builder | Multiple issues in Ethernet package generator |
| PB-79 | Studio Package Builder | Package Generator does not place parameters from KADSWI108 |

| Issue # | Project | Description |
|---------|-----------------------------|--|
| PB-98 | Studio Package Builder | DAS Studio PCM frame loses focus when zooming in |
| PKG-54 | Studio Packages Tab General | Navigating between modules when Packages tab is in context can result in slow performance of DAS Studio |
| PKG-364 | Studio Packages Tab General | Mouse 'Wait' icon is not always displayed when waiting for DAS Studio to complete a task |
| PKG-436 | Studio Packages Tab General | The IRIG-106 packages tab does not let you define everything that you might want for an IRIG-106 package definition such as FCC and URC. |
| PKG-439 | Studio Packages Tab General | DAS Studio does not prevent user from creating a slave PCM packages, these are automatically created at compile time |
| PKG-472 | Studio Packages Tab General | DAS Studio does not automatically update certain fields when manually creating Ethernet packets e.g., Stream ID may be repeated |
| PKG-497 | Studio Packages Tab General | Packages tab does not always show Package Grid when opened the first time |
| PKG-501 | Studio Packages Tab General | For MIL-STD-1553 Mode code 17 messages, the sub-sub address map is not supported on MIL-STD-1553 messages |
| PKG-503 | Studio Packages Tab General | User cannot set occurrences for ARINC ARI002 package via grid, but can set the occurrences under preferences |
| PKG-520 | Studio Packages Tab General | Packages tab is not refreshed when deleting a module |
| PKG-580 | Studio Packages Tab General | Users may experience poor Memory performance when switching between tabs multiple times |
| PKG-594 | Studio Packages Tab General | UDP Destination Port defaults to 0 for iNET-X Placed packets |
| PKG-598 | Studio Packages Tab General | Refresh issue when Delete process package filter for EBM, have to save and re-open the task file |
| PKG-603 | Studio Packages Tab General | Package Rate for Packetizer Packets can be set but has no impact as it is overwritten on Verify |
| PKG-669 | Studio Packages Tab General | Placement Preferences not displayed as selected |
| PKG-692 | Studio Packages Tab General | Transmission assistance does not update when fragmentation error is caused by the placed content grid |
| PKG-702 | Studio Packages Tab General | Changing burst parameter properties in the Placed Data grid replaces the burst parameter with a single instance |
| PKG-703 | Studio Packages Tab General | Burst parameter occurrences not displayed correctly in the Placed Data grid |
| PKG-729 | Studio Packages Tab General | BCU101C Syncword not updating correctly |
| PKG-742 | Studio Packages Tab General | Clicks off the selected parameter before to place it |
| PKG-743 | Studio Packages Tab General | It takes 5 seconds to refresh PCM frame for every placement |
| PKG-749 | Studio Packages Tab General | Ghost discrete parameter appears in XidML file when saving without source parameters |
| RIB-3 | Studio Ribbon Bar | If you are editing a table cell and then select a menu option, i.e. Save, the changes in the cell will be lost. |

| Issue # | Project | Description |
|---------|-----------------------------|---|
| SAC-4 | Standalone Compiler | Das Studio Program - XidML file is compiled whether it has output or not - No warnings or errors |
| SAC-70 | Standalone Compiler | Disable Serial Number synchronizer options on UI as it is not supported |
| SCS-126 | Single Chassis Scheduler | The folder used for storing compiler debug files is not cleared out at start of compilation |
| SCS-379 | Single Chassis Scheduler | 32 bit registers are presented correctly in BCU140B packets but are reversed in MBI103B messages |
| SCS-388 | Single Chassis Scheduler | Overrun detected error with more than 3.3M Ethernet transfers |
| SCS-477 | Single Chassis Scheduler | On the BIT101 Users can create a Trigger Condition and not assign a parameter to it. They will not be warned until compile time |
| SCS-487 | Single Chassis Scheduler | Compiler error with synchronous DEC103 - Failed to generate timing window for DECData |
| SEB-9 | Studio Ethernet Builder | Select Conversion Units dropdown and it changes value of the preceeding conversion unit entered |
| SET-47 | Studio Settings Tab General | DAS Studio GUI does not detect and warn users if two Packetizer channels use the same Stream ID. Error is shown at compile time |
| SET-51 | Studio Settings Tab General | Updating TDC002D parameter 'Range Min/Max' is not done automatically by UI dependent on the look up file selected |
| SET-53 | Studio Settings Tab General | Updating ADC113B 'Range Min/Max' and 'Excitation amplitude' is not done automatically by UI dependent on the algorithm reference selected |
| SET-153 | Studio Settings Tab General | KADADC135 and KADADC136 Changing Excitation Mode from Voltage to Current, or vice versa, does not automatically update the amplitude to a valid figure for that setting |
| SKD-14 | Studio Hardware Discovery | Discovery tools ask for irrelevant Gateway Input range when discovery Ground Station Modules |
| SKD-16 | Studio Hardware Discovery | 'IP Address' range validation is not applied on discovery gateway definition |
| SKD-20 | Studio Hardware Discovery | Discovery tool does not state 'no hardware found' when Discovery fails, just reports Discovery complete |
| SKD-82 | Studio Hardware Discovery | Cannot save file and error is issued when the IP of a switch is added to discovery |
| SKD-87 | Studio Hardware Discovery | Discovery will always return a AXNCHS16U no matter what the chassis size when using AXNBCU401 |
| SKD-100 | Studio Hardware Discovery | Discover returns an exception when discovering through NET/SWI/101/C to Axon |
| SKD-112 | Studio Hardware Discovery | Discover AXN/ABM/401 - Exception Invalid XidMLFile:skilpyu.xkq , Inner Exception System.ArgumentNullException: Value cannot be null. Parameter name: source |
| SKD-119 | Studio Hardware Discovery | Systems programmed with 3.4.10 cannot be discovered with 3.4.11 using a AXNBCU401 as it is NOT supported. |
| SKD-122 | Studio Hardware Discovery | DAS Studio discovers the AXNTDC401 with configuration errors |
| SKD-129 | Studio Hardware Discovery | DAS studio does not report an error when discovering 2 Axon chassis with the same IP address |
| SKD-141 | Studio Hardware Discovery | Discovering axon hardware fails with errors, 3.4.21 #10136 |
| SMS-12 | Studio Message Server | Localisation Issue:Exception from HRESULT |

| Issue # | Project | Description |
|---------|---------------------------------|---|
| SPC-86 | Studio Power Calculator | Possibility to enter the current directly instead of a load in ohms |
| SPC-98 | Studio Power Calculator | Power calculator shows an incorrect error when power calculations are correct - this is due to incorrect values in the warning and error percentages |
| SPC-99 | Studio Power Calculator | DAS Studio user manual shows incorrect values in the warning and error percentages for Power calculator shows power calculator |
| SPC-103 | Studio Power Calculator | power consumption in line |
| SPG-23 | Studio Package Grid | PCM package display grid may require a refresh after Verification or Programming |
| SPG-25 | Studio Package Grid | DAS Studio allows Users to add Parameters to Bus Monitor Packages that are already full, but does not report any warning |
| SPG-26 | Studio Package Grid | DAS Studio Packages display may require a refresh after adding parameters |
| SPLT-3 | Studio Package Links Table | PackageRate on PCM links is not automatically updated when the bit rate is changed |
| SPPT-10 | Studio Package Properties Table | DAS Studio fails to auto-validate 'data type' for iNet-X packages |
| SPPT-33 | Studio Package Properties Table | Illegal Stream ID settings may only be caught at compile time |
| SPRP-34 | Studio Parameters Palette | Default Parameters list may be shown when adding parameter to a package, instead of the parameters associated with the task. Click on 'This file' to get the correct parameter list |
| SPT-5 | Studio Packages Table | Need a limitation on the maximum number of parameters/words that can be placed into different types of packages |
| SPT-9 | Studio Packages Table | In some scenarios, validation of parameter name uniqueness may not work as expected |
| SPT-14 | Studio Packages Table | Overlap error when adding parameters from table |
| SPT-81 | Studio Packages Table | Invalid placement location indication for all parameters when packet size is more than maximum iNET-X size |
| SQL-28 | Studio Quicklook | kQuicklook will report an error when uninstalling after DAS Studio 3.4.1 was installed or uninstalled |
| STV-6 | Studio Verify | DAS Studio does not automatically save changes to the XidML file. User must click save to ensure no changes are lost |
| STV-10 | Studio Verify | Using Auxiliary files is not supported in DAS Studio |
| SUAR-24 | Studio Serial Builder | UBM-103 does not support idle time - Some parsing options such length only on Serial Builder for UBM-103 are incorrect |
| SUAR-26 | Studio Serial Builder | Serial Builder error after package renaming |
| SUM-21 | Studio User Manual | Axon Discovery should mention that it also retrieves the xidML stored on the Axon controller |
| TLS-31 | Studio Tools General | DAS Studio does not manage Sensors and input channels calibration |
| TLS-80 | Studio Tools General | The given key was not present in the dictionary |
| TTPI-5 | TTP Importer | Cancelling TTP importer while removing links may cause DAS Studio to become unstable |
| XACS-13 | XidML API | Mode code 17 sub sub address map not supported on MIL-STD-1553 messages |
| XACS-18 | XidML API | Adding 1553 message with " " in the message name creates invalid XidML |
| XDF-36 | xDefML File | Analog-IRIG_BOut is defined under Inputs on a KAMTCG102C |

| Issue # | Project | Description |
|---------|-------------|---|
| XDF-135 | xDefML File | RS422_OUT can act as either X-sync out or IRIG-Out on all TCG Modules. However, the Outputs only ever show RS422_Out, this stops users connecting IRIG_Out to IRIG_in on other modules in the GUI |
| XDF-144 | xDefML File | KADADC129S1 ExcitationAmplitude default value is 0.2 on the datasheet and 5 in DAS Studio |
| XDF-146 | xDefML File | KADADC109CS1 ExcitationAmplitude default value is 0.2 on the datasheet and 5 in DAS Studio |
| XDF-147 | xDefML File | 'BalanceTolerance' and 'Balance Target' ranges are not defined in datasheets of Analog Modules |
| XDF-200 | xDefML File | Cannot connect IRIG-B_out from TCG102C to NETSWI004 digital IRIG-B_In |
| XDF-327 | xDefML File | DAS Studio UI will allow BitRates lower than what is achievable in the hardware on BCU101 modules |
| XDF-328 | xDefML File | SSRCHS001B DAS Studio Setting Memory Utilization Threshold default value should be 0 |
| XDF-393 | xDefML File | KADMSB103C should not show bus ID with values 0 to 7 |
| XDF-394 | xDefML File | DAS Studio allows the user to define the Max/Min temperatures per channel, needs to be the same for all channels |
| XDF-444 | xDefML File | Wrong Datasheet shows up when clicking on datasheet for EBM-102-B |
| XDF-446 | xDefML File | Pull-down Resistor is hardwired to Disabled when D-E is selected in the AXN-ADC-405. This should be optional |
| XDF-449 | xDefML File | Clicking on the datasheet of the CDI101 will load the CDC101 datasheet |

Issues fixed in this release

| Issue # | Project | Description |
|----------|--------------------|--|
| DAS-1722 | DAS Studio General | UBM/UAR module : Word definition in byte, offset counted in bytes or in words: either everything in bytes or everything in words |
| DAS-1932 | DAS Studio General | IP programmer could be a bit fancier by using SNMP broadcast |
| DAS-1937 | DAS Studio General | It will be nice to change the occurrences by multiset in the package tab when building Ethernet packets |
| DAS-1954 | DAS Studio General | customize the main DAS Studio tab |
| DAS-1959 | DAS Studio General | The number of occurrences in a MEM packet shown by DAS Studio is wrong |
| DAS-2125 | DAS Studio General | be nice if Standalone compiler could have its own installer |
| DAS-2384 | DAS Studio General | a way to know if a parameter has already been placed in an Ethernet packet |
| DAS-3405 | DAS Studio General | Some warnings should be information |
| DAS-3770 | DAS Studio General | NETREC006B: MAC Address value is reversed for the following parameters: statusDestMAC & eventDestMAC |
| DAS-3854 | DAS Studio General | video is gone if a standard parameter is placed using smart mode |
| DAS-4289 | DAS Studio General | BCU101 should not allow bitrate 4194304 bps i.e. it will create too much jitter for a decom to get lock |
| DAS-4433 | DAS Studio General | ENC106B should be removed from the instrument palette |
| DAS-4501 | DAS Studio General | In a large distributed AXN and KAM system high speed PCM, MCS packets for PCM transmission may contain stale data |

| Issue # | Project | Description |
|----------|--------------------------------|--|
| DAS-4503 | DAS Studio General | Transmission Assistant cannot place a PCM frame with smart placement on - the same frame can be placed manually and verifies |
| DAS-4506 | DAS Studio General | Bridge Balancer and ADC136: Cannot find bracketed root for parameter |
| DAS-4547 | DAS Studio General | AXN-ADC-401 should only show a ReadCounter parameter and the name should be consistent with other cards |
| DAS-4595 | DAS Studio General | burst parameter shall follow the smart placement rule if enable |
| DAS-4619 | DAS Studio General | System.ArgumentException: An item with the same key has already been added - this error points to a possible duplication in the package occurrence |
| DAS-4670 | DAS Studio General | MinorFrameNumber tag not in xidML file if 1 minorframe defined in the PCM |
| DAS-4681 | DAS Studio General | Xidml cannot be loaded: When bits per word in PCM frame changed to 8, xidml is updated with Offset_Bytes on compile. |
| DAS-4692 | DAS Studio General | Unable to load XidML in 3.4.16 while it can be loaded in 3.4.25 due to the AXNADC405 xDefML file |
| DAS-4695 | DAS Studio General | MBM401 bad data |
| DAS-4699 | DAS Studio General | 'More Parser Slots used than are available. Attempting to use slot 0 for parser |
| DAS-4704 | DAS Studio General | DAS Studio crashes after importing an Axon parameter to the DAC001 |
| DAS-4749 | DAS Studio General | AXNADC404 needs power cycling after balancing |
| NAV-99 | Studio Navigator | Can't drag a module from one slot to another using the mouse |
| PKG-760 | Studio Packages Tab General | System.Dynamic.ExpandoObject displayed on destination IP address field of EBM101 Package |
| SAC-7 | Standalone Compiler | standalone compiler in Linux |
| SAC-8 | Standalone Compiler | Ability to switch off the message viewer |

GTS SDK 3.3

Modules supported in this release

See GTS SDK 3.3 data sheet for list.

New features in this release

See GTS SDK 3.3 data sheet.

Known issues in this release

| Issue # | Project | Description |
|-----------|---------|---|
| GDSDK-182 | GTS SDK | SystemDefinitionAPI does not allow manipulating major frame of PCM. |
| GDSDK-181 | GTS SDK | GetGTSStatus(ex) has very poor performance. |
| GDSDK-180 | GTS SDK | GetBufferParameterMapping failed at the SyncWord at front. |
| GDSDK-178 | GTS SDK | Need to be able to retrieve part reference from type number. |
| GDSDK-161 | GTS SDK | Out of lock (LossStatusCount) when testing GTS/DEC/005/C with 20M, NRZ-L and Bit-sync. This is none issue when using Borland C++ sample code. |
| GDSDK-157 | GTS SDK | Overflow at SDK Ring Buffers occurs when going above 6.5MHz. This is none issue when using Borland C++ sample code. |

| Issue # | Project | Description |
|-----------|---------|--|
| GDSDK-149 | GTS SDK | Function to return the card serial number is required. |
| GDSDK-36 | GTS SDK | SDK Installer always installs "MicrosoftWindowsInstaller 3.1" regardless of whether or not it was already installed. This will affect the installation time. |
| GDSDK-15 | GTS SDK | SystemDefinitionAPI: Does not support setting up Major Frames. |
| GDSDK-14 | GTS SDK | GroundStationAPI: Does not support setting up "Name" on FrameWords in a PCM Package. |
| GDSDK-3 | GTS SDK | SystemDefinitionAPI: Rename IMinorFrameWords.RemoveWord (indexToRemove) parameter as its' causing confusion. |

Issues fixed in this release

| Issue # | Project | Description |
|-----------|---------|--|
| GDSDK-177 | GTS SDK | SystemDefinitionAPI writes '0,2' instead of '0.2' at 'Acquisition Loop Bandwidth' which make it failed to be read. |
| GDSDK-176 | GTS SDK | SystemDefinitionAPI failed to read XidML when it contains 'Generic PC'. |

Products supported by DAS Studio 3

For a list of products supported by DAS Studio 3, see the *DAS Studio 3* data sheet.

Legacy modules not supported by DAS Studio 3

| Module |
|--------------------|
| KAD/ADC/001 |
| KAD/ADC/002/B/100m |
| KAD/ADC/002/B/1V |
| KAD/ADC/002/C/100m |
| KAD/ADC/002/C/10V |
| KAD/ADC/002/C/1V |
| KAD/ADC/003 |
| KAD/ADC/003/B |
| KAD/ADC/005 |
| KAD/ADC/006 |
| KAD/ADC/009/QB100 |
| KAD/ADC/009/QB350 |
| KAD/ADC/009/S1 |
| KAD/ADC/009/S2 |
| KAD/ADC/009/S4 |
| KAD/ADC/010/B |
| KAD/ADC/010/C |
| KAD/ADC/011/B/X1 |
| KAD/ADC/011/C/X1 |
| KAD/ADC/021 |
| KAD/ADC/021/RT |
| KAD/ADC/106 |
| KAD/ADC/109/S1 |
| KAD/ADC/117 |
| KAD/ADC/126 |
| KAD/BCU/001 |
| KAD/BCU/001/B |
| KAD/BCU/001/CX |
| KAD/BCU/003 |
| KAD/BCU/003/SB |
| KAD/BCU/101 |

| Module |
|------------------|
| KAD/BCU/102 |
| KAD/BCU/102/B |
| KAD/BCU/104 |
| KAD/BCU/105 |
| KAD/BCU/105/B |
| KAD/CBC/101 |
| KAD/CBC/102 |
| KAD/CBI/101 |
| KAD/DEC/002 |
| KAD/DPI/002 |
| KAD/DSI/003 |
| KAD/ENC/004 |
| KAD/ENC/004/B/ET |
| KAD/ENC/004/ET |
| KAD/ENC/005/B/RS |
| KAD/ENC/006/HA1 |
| KAD/ENC/006/HA2 |
| KAD/ENC/006/HA3 |
| KAD/ENC/006/HA4 |
| KAD/ENC/006/X1 |
| KAD/ENC/006/X2 |
| KAD/ENC/006/X5 |
| KAD/ETH/001/B |
| KAD/ETH/001/C |
| KAD/LDC/001/01 |
| KAD/MAT/001/B |
| KAD/MBC/001 |
| KAD/MBI/001 |
| KAD/MBI/001/B |
| KAD/MBI/102/00 |
| KAD/MBI/103 |
| KAD/MDC/001 |
| KAD/MDC/104 |
| KAD/MEM/004/4G |
| KAD/MSB/001 |
| KAD/MSB/001/B |
| KAD/MSB/002/B |

| Module |
|-----------------------|
| KAD/MSB/003 |
| KAD/MSB/003/B |
| KAD/MSB/103 |
| KAD/PBM/002 |
| KAD/PBM/002/BA1 |
| KAD/RTC/002 |
| KAD/SDC/002/90V |
| KAD/SDI/001 |
| KAD/SIG/101 |
| KAD/TCG/001 |
| KAD/TCG/001/B |
| KAD/TDC/001/10K |
| KAD/TDC/001/2K2 |
| KAD/TDC/002/ET/00 |
| KAD/TDC/002/B/00 |
| KAD/TDC/002/B/ET/00 |
| KAD/TDC/004 |
| KAD/TDC/004/ET |
| KAD/TDC/006 |
| KAD/TDC/006/RT |
| KAD/UAR/001 |
| KAD/UAR/002/B |
| KAD/UAR/003 |
| KAD/UAT/101 |
| KAD/UTL/001 |
| KAD/UTL/102 |
| KAD/UTL/102/X1 |
| KAD/UTL/102/X2 |
| KAM/ADC/004 |
| KAM/ADC/004/05/FB/350 |
| KAM/ADC/009/S1/5KHZ |
| KAM/ADC/009/S2/ET/MA |
| KAM/ADC/011/10V |
| KAM/ADC/012/10V |
| KAM/ADC/013 |
| KAM/ADC/014/10V |
| KAM/ADC/019/100 |

| Module |
|------------------|
| KAM/CDC/001 |
| KAM/CDC/001/B |
| KAM/CDC/001/C |
| KAM/DPI/001 |
| KAM/ENC/002 |
| KAM/ENC/003 |
| KAM/ENC/006 |
| KAM/ENC/006/X3 |
| KAM/ENC/006/X4 |
| KAM/ENC/007 |
| KAM/MAT/001/00 |
| KAM/MEM/001 |
| KAM/MEM/002/00 |
| KAM/MEM/003 |
| KAM/MEM/003/B |
| KAM/MEM/003/C |
| KAM/MEM/003/D |
| KAM/MSB/002 |
| KAM/MSB/002/B/TC |
| KAM/TCG/102 |
| KAM/TDC/003 |
| KAM/UAR/002 |
| KAM/VID/002 |
| MKM/ADC/005 |
| MKM/SDC/001 |
| MKM/CHS/02U |
| MKM/ADC/014/R1 |
| MKM/ADC/014/R2 |
| MKM/BCU/101 |
| MKM/BCU/101/B |
| MKM/UAR/102 |
| NET/SWI/004/EM1 |
| SSR/CHS/001 |

Acronyms

This document lists common acronyms and terms used in telemetry. For more telemetry terminology, see *TEC/NOT/026, Dictionary of telemetry terms*.

AAAF

Analog Anti-Aliasing Filter. See [AAF](#).

AAF

Anti-Aliasing Filter. A filter which reduces aliasing effects by restricting the bandwidth of the sampled signal to approximately satisfy the sampling theorem, that is, most of the signal energy is kept within a bandwidth of half of the sampling frequency.

ACK

ACKnowledgment code. The communications code sent from a receiving station to a transmitting station to indicate that it is ready to accept data. It is also used to acknowledge the error-free receipt of transmitted data.

Acra KAM-500

Acra's flagship modular data acquisition product.

A/D

Analog to Digital. Conversion of analog signals to digital.

AES

Advanced Encryption Standard. An NIST-standard cryptographic cipher that uses a block length of 128 bits and key lengths of 128, 192 or 256 bits. Officially replacing the Triple DES method in 2001, AES uses the Rijndael algorithm. AES can be encrypted in one pass instead of three, and its key size is greater than Triple DES's 168 bits.

AHeAD

Aircraft Health Analysis and Diagnosis. Embraer system for predictive maintenance.

AHUMS

Adaptive HUMS. See [HUMS](#).

ARO

After Receipt (of) Order.

ARP

Address Resolution Protocol. A protocol used to obtain a node's physical hardware address.

ARTM

Advanced Range TeleMetry program. Tier 1 products use SOQPSK techniques to double the data rate in a given RF bandwidth; Tier II uses multi-h techniques to treble it. PCM/FM is sometimes referred to as Tier 0.

ATP

Acceptance Test Procedure. The final phase of design validation, which ensures that each component of a customer's system (hardware and software) work together.

BAG

Bandwidth Allocation Gap. Allocated data transmission interval in an ARINC 664 Part 7 network.

Bandwidth

The frequency range occupied or required by a signal. Pulse Code Modulation (PCM) signals contain harmonics that are usually removed by pre-modulation filtering to reduce the bandwidth needed for telemetry transmission or tape recording. However, insufficient bandwidth may result in the loss of essential information and prevent the recovery of PCM encoded data.

Barker codes

A selection of bits to be used as frame sync words so as to minimize the probability of false lock. For more information, see the Reference section of the *Applications Handbook*.

BDS

Best Data Selector. Diversity receiver method where the stream with the least data errors, such as sync word slips, and sync word bit errors, is used.

BER

Bit Error Rate. The average number of bits transmitted in error. Every data link has a theoretical minimum error rate depending on the noise present. A reasonable encoder/decoder system linked via copper would have a BER of 10⁻⁹. BERs are specified for encoders, data links (especially radio), bit syncs, and decoders.

BIO-L

Bi-phase Level. See [PCM Codes](#).

BIO-M

Bi-phase Mark. See [PCM Codes](#).

BIO-S

Bi-phase Space. See [PCM Codes](#).

BOM file

File used to store original hardcopy BOMs (Bill of Materials).

bps

Bits Per Second. The measurement of the speed of data transfer in a communications system. Note that Bps is used to denote Bytes Per Second.

BSS

Best Source Selector. Diversity receiver method where the stream with the best signal-to-noise ratio is used.

CAIS

Common Airborne Instrumentation Systems. Developed by the U.S. Department of Defense to promote standardization commonality and interoperability among aircraft test instrumentation systems.

CAR

Corrective Action Report. A report into any defect in any product or procedure.

cBIT

Continuous Built-In-Test.

CBM

Condition-Based Maintenance. Used primarily to predict when to service the machine rather than to repair it, but no clear distinction. Originally used for industrial machines and generators, then for airplanes.

COFDM

Coded Orthogonal FDM. See [FDM](#).

COMSEC

Compound word for COMmunications SECurity.

COO

Confirmation of Order. The document issued to customers that confirms terms and conditions, price, and quantities of the last revision of RFQ.

COTS

Commercial Off-The-Shelf. Refers to ready-made merchandise that is available for sale.

CSMA/CA

Carrier Sense Multiple Access/Collision Avoidance. A transmission protocol that attempts to avoid collisions that can occur when two nodes attempt to transmit at the same time on the bus rather than detect them, as in CSMA/CD.

CSMA/CD

Carrier Sense Multiple Access/Collision Detection. The Local Area Network (LAN) access method used in Ethernet. When a device wants to gain access to the network, it checks to see if the network is quiet (senses the carrier) before it begins transmitting its data. Collision Detection allows for the node to be aware if another node begins to transmit causing their frames to collide.

CSS

Correlated Source Selection. Diversity receiver method where two streams with roughly the same signal-to-noise ratio and data error rates are aligned (correlated) and voting or soft-bits are used to decide on a bit-by-bit basis.

D/A

Digital to Analog. Conversion of digital signals to analog.

DAS

Data Acquisition System.

DAS Studio 3

DAS Studio 3 uses a multi-threaded design, which utilizes multi-core processors to improve performance. DAS Studio 3 lets you configure Data Acquisition Units (DAUs), network

switches, recorders and ground stations in an integrated environment.

DAU

Data Acquisition Unit.

dB

Decibel. A unit which indicates a ratio of power between two signals.

dBc

Decibels relative to carrier. A common measurement (in decibels) in Radio Frequency (RF) engineering to specify the power of a sideband in a modulated signal relative to the carrier.

DHCP

Dynamic Host Configuration Protocol. A protocol that automatically assigns IP addresses to client stations logging onto an IP network.

Diversity Combining

A method, based on signal power, of switching between diverse receivers.

Diversity receivers

Using two or more streams to reduce lost data. *Temporal diversity* - sending data twice in the one stream. *Frequency diversity* - using two frequencies. *Spatial diversity* - using two receivers at different physical locations. *Polar diversity* - using left and right hand (I/Q) receivers.

DM-M

Delay Modulation Mark. See [PCM Codes](#).

DM-S

Delay Modulation Space. See [PCM Codes](#).

DNS

Domain Name System. A system for converting host names and domain names into IP addresses on the Internet or on local networks that use the TCP/IP protocol.

DST

Data Sheet. Every product must have a data sheet outlining the features, applications specifications, and revision history as well as any other technical data required to use it. The front leaf of the data sheet is used by Sales as a short-form data sheet which they give to potential customers.

DV

Design Verification. The stage between handover after unit test and product release; it culminates in a Design Verification Report (DVR). DV is also an acronym for the Design Verification department.

DVP

Design Verification Plan.

DVR

Design Verification Report. Every active NRE culminates in a DVR. If written after a design verification phase, it documents all the tests done and the results. If written after the suspension of an NRE, it states the reason(s) for the suspension.

Eb/No

Bit Energy/Noise Spectral Density. A measure of the signal-to-noise ratio.

EEPROM

Electrically Erasable Programmable ROM. Re-writable memory that holds its content without power. EEPROMs have a lifespan of between 10k and 100k write cycles, which is considerably greater than the EPROMs that preceded them.

EHUMS

Engine HUMS. See [HUMS](#).

ENOB

Effective Number Of Bits.

ES

End System. ARINC 664 Part 7 end-device that produces data to be transmitted over the ARINC 664 Part 7 network.

ESS

Environmental Stress Screening. Process of exposing products to stresses in order to force latent defects to manifest themselves by permanent or catastrophic failure during the screening process.

FAT32

An enhancement of the File Allocation Table file system that supports memory media with capacities up to 2 TB.

FAQ

Frequently Asked Questions. Questions asked by both customers and Curtiss-Wright employees.

FEC

Forward Error Correction. A means of adding extra bits to reduce bit error rates. Common methods are convolutional, reduced parity, and turbo coding.

FDM

Frequency Division Multiplexing. Transmitting multiple data signals simultaneously over a single wire by using multiple carriers, each having a unique center frequency. Each data stream, such as text, voice or video, is placed into a separate carrier that is modulated by various methods.

FDAU

Flight Data Acquisition Unit.

FIFO

First In First Out. A storage method that retrieves the item stored for the longest time.

FQPSK

Feher-patented QPSK. See [QPSK](#).

FSK

Frequency Shift Keying. A simple digital modulation technique that uses two frequencies for 0 and 1. See [QPSK](#).

FSR

Full Scale Range.

FTI

Flight Test Instrumentation. The instrumentation system, including mounting brackets, that is used on an aircraft for flight test purposes. It is usually orange in color in order to distinguish it from standard equipment.

FTP

File Transfer Protocol. File transfer protocol that runs over TCP/IP.

FUMS

Fleet Usage Monitoring System. HUMS for a particular fleet of aircraft (not very common).

GAHMM

Global Aircraft Health Monitoring and Management. Airbus system for predictive maintenance.

GHUMS

Generic HUMS. See [HUMS](#).

GSX-500

Suite of ground-station software products. Some of these products are third-party.

GTS-500

Suite of ground-station hardware products. Some of these products are third-party.

Hamming code

A method by which extra bits can be added to a word so as to detect one (or more) bit errors (and possibly fix them).

hDefML

Hardware Definition Markup Language. A hardware definition schema, used by Acra software to program Acra hardware.

HUMS

Health and Usage Monitoring System. Mostly (and originally) for helicopters. Focused on rotating parts (gear box, shaft) with specific software for frequency analysis and cumulative databases. Variants include E-HUMS (engines), T-HUMS (Turbo prop shafts).

iBIT

Initiated Built-In-Test.

ICMP

Internet Control Management Protocol. An IP protocol used to send error and control messages. The most widely known ICMP function is the Ping command which echoes a message across the network which allows the communication path between end nodes to be tested.

IEEE

Institute of Electrical and Electronic Engineers. A membership organization that includes engineers, scientists, and students in electronics and allied fields.

iDefML

An XML file for each piece of hardware, which outlines the XidML schemas that apply and the constraints imposed for each setting and a pointer to the data sheet. For Acra KAM-500 modules, it also contains register definition and EEPROM generation sections.

IGMP

Internet Group Management Protocol. The protocol that governs the management of multicast groups in an IP network.

ISI

InterSymbol Interference. A form of distortion of a signal in which one symbol interferes with subsequent symbols. This is an unwanted phenomenon as the previous symbols have a similar effect as noise, thus making the communication less reliable.

IRIG

Inter-Range Instrumentation Group. The standards body of the Range Commanders Council (RCC).

IRIG time codes

The different time codes have alphabetic designations. A, B, D, E, G, and H are the standards currently defined. The main difference between codes is their rate, which varies between one pulse per minute and 10,000 pulses per second.

IRIG 106 (Ch.4 Ch.8 Ch.10)

Inter Range Instrumentation Group. IRIG-106 is the main standard in our industry, containing chapters on PCM (ch. 4), MIL-STD-1553 snarfing (ch. 8), solid state storage (Ch.10), and RF standards (appendices).

iNET

Integrated Network Enhanced Telemetry. A program, led by Southwest Research Institute that is developing a standard for next-generation data acquisition systems. A key objective of iNET is to adopt open standard network-based technologies to ensure reduced costs and equipment interoperability.

Since the iNET standard is not released as of 2012, iNET-X is an expedited implementation of the iNET standard that

provides the core functionality, technologies, and standards that are outlined in the iNET standard and unlikely to change in the released version of the standard. For the end user, iNET-X provides a phased, safe, and gradual transition towards network based technologies.

IP

Internet Protocol. The network layer protocol OSI stack. The IP layer provides logical IP source and destination addresses for packets that are transmitted across the network.

IP address

The address of a device attached to an IP network. Every network node must have a unique IP address for each network connection. The format of an IP (version 4) address is a 32-bit numeric address, written in dotted quad format. Each number can be zero to 255. For example, 1.160.10.240 could be an IP address. Some IP addresses are reserved. For more information, see <http://www.iana.org/numbers>

IPC

Institute for Printed Circuits. Class 3 is the best standard for visual inspection of assembled Printed Circuit Boards (PCBs).

IP subnet addressing

Routers, or gateways, are used to separate networks. The router breaks the network into multiple subnets. This result may seem familiar as Class A, B, and C addresses have a self-encoded or default subnet mask built in; class A network address - 255.0.0.0: class B network address - 255.255.0.0: class C network address - 255.255.255.0.

ISO 9000

ISO 9000 is a family of standards for quality management systems. ISO 9000 is maintained by ISO, the International Organization for Standardization. Adhering to an ISO 9000 standard certifies that formalized business processes are being applied.

ISHM

Integrated Systems Health Management. Similar to L/ESS.

JIRA

Curtiss-Wright's internal issue-tracker software.

KAM chassis

Consists of housing, Power Supply Units (PSU), and backplane.

kbps

KiloBits Per Second. A unit of data transfer rate equal to one thousand bits per second.

ksps

KiloSamples Per Second. One thousand samples per second.

kHz

KiloHertz. One thousand cycles per second. It is used to measure the transmission frequency of electronic devices, including channels, buses, and the computer's internal clock.

KGV-69

A chip designed to be a 'bare bones' encryptor for use in very high risk applications. The KGV 69 encrypts and decrypts serial data at up to 50 Mbps.

kV

KiloVolt. One thousand volts.

L/ESS

Loads and Environmental Spectra Survey. Mostly airframe strain gauges.

LNA

Low-Noise Amplifier. An amplifier used in communication systems to amplify very weak signals.

LXI

LAN eXtensions for Instrumentation. A standard developed by the LXI Consortium. The LXI standard defines devices using open-standard LAN (Ethernet) for system inter-device communication.

mA

MilliAmpere. One thousandth of an amp.

MAC

Medium Access Control. The MAC layer adds source and destination hardware address identification to MAC frames transmitted across the Ethernet. The MAC layer also defines the protocol governing the transmission of Ethernet frames over the medium. The MAC layer of wired IEEE 802.3 Ethernet is CSMA/CD whilst the MAC layer of wireless IEEE 802.11 is CSMA/CA.

MAC address

A hardware address which uniquely identifies each node of a network. In IEEE 802 networks, the Data Link Control (DCL) layer of the OSI reference model is divided into two sublayers—the Logical Link Control (LLC) layer and the Media Access Control (MAC) layer. The MAC layer interfaces directly with the network medium. Consequently, each different type of network medium requires a different MAC layer.

Matched filter

The optimum filter required to maximise the signal-to-noise ratio in receivers. The GTS/DEC/003 uses a fully programmable digital matched filter.

Matches to lock

The number of valid sync words (1-16) required after loss before the data is considered valid.

Max

Error, including drift over temperature. Contrast with [Typical](#).

Mbps

MegaBits Per Second. One million bits per second. (If the B is upper case, it is MegaBytes per Second—one million bytes per second.)

MBps

MegaBytes Per Second. One million bytes per second. 1 MB = 1024 kB.

MHz

MegaHertz. One million cycles per second. It is used to measure the transmission speed of electronic devices, including channels, buses, and the computer's internal clock.

MIL-STD

Military Standard. A detailed technical specification for a product that is purchased by a U.S. military agency.

Misses to loss

The number of sync words (1-16) which fail the match tolerance before data is considered invalid.

ms

MilliSecond. One thousandth of a second.

Msp/s

MegaSamples Per Second. One thousand samples per second.

MTBF

Mean Time Between Failures. The mean (average) time between failures of a system.

MTU

Maximum Transmission Unit. Maximum packet size allowed to be carried on the network segment. Any packet that exceeds the MTU is fragmented by the intermediate router or switch or may be discarded. Typically the MTU of an Ethernet frame is 1522B on an IEEE 802.3 100BaseTX Ethernet network segment.

mV

MilliVolt. One thousandth of a volt.

NDA (IP)

Non-Disclosure Agreement (Intellectual Properties). A legal contract, between at least two parties, that outlines confidential materials or knowledge which the parties wish to share. As part of the contract, the parties agree not to disclose information covered by the agreement.

NRE

Non-Recurring Engineering. Any task to be carried out by product development becomes an active NRE. Every active NRE culminates in a DVR.

NRZ-L

Non-Return to Zero Level. See [PCM Codes](#).

NRZ-M

Non-Return to Zero Mark. See [PCM Codes](#).

NRZ-S

Non-Return to Zero Space. See [PCM Codes](#).

ns

Nano Second. One billionth of a second (1E-9 seconds).

NTP

Network Time Protocol. Internet time synchronization protocol with millisecond accuracy.

OLM

Operational Loads Monitoring. Mostly airframe strain gauges.

OSI (model)

Open System Interconnection. An ISO standard for worldwide communications that defines a framework for implementing protocols in seven layers. Control is passed from one layer to the next, starting at the application layer in one station, proceeding to the bottom layer, over the channel to the next station and back up the hierarchy.

Package

An element of XidML that describes how data is transported. For example, when starting kExcel we have to select the package (PCM format) to be loaded in SAM/DEC/007.

PAM

Pulse Amplitude Modulation. Pulse modulation in which a voltage is sampled periodically, then transmitted as an analog signal whose amplitude is proportional to the sampled voltage. Because PAM is susceptible to transmission noise, it has been replaced by PCM in most telemetry applications. For more information, see *TEC/NOT/024, Evolution of Pulse Code modulation (PCM)*.

Parser

Primarily a Curtiss-Wright word for a bus monitor that stores whole packets in triple buffers (received, interim, and read) so that specific words from specific packets can be included coherently.

pBIT

Periodic Built-In-Test.

PCB

Printed Circuit Board. A rigid, flat board that holds chips and other electronic components. A PCB legend on a PCB indicates its part number and serial number.

PCM

Pulse Code Modulation. The primary way analog signals are converted into digital form by taking samples of the waveforms from 8 to 192 thousand times per second (8 to

192 kHz) and recording each sample as a digital number from 8 to 24 bits long.

PCM Codes

Any of several encoding schemes used to convert a parallel digital value into a serially transmitted sequence of binary code. For more information on PCM codes, see *TEC/NOT/027, IRIG 106-96 chapter 4*.

PHM

Prognostic Health Monitoring. Like CBM, originally used for wind turbines and generators.

PHUMS

Prognostic HUMS. See [HUMS](#).

PING

Packet Inter-Network Groper (ICMP Echo Request). An Internet utility used to determine whether a particular IP address is reachable by sending out a packet and waiting for a response. PING is used to test and debug a network as well as see if a user or server is online.

PO

Purchase Order. Document issued by a buyer to a seller, indicating the type, quantities and agreed prices for products or services the seller will provide to the buyer.

Port

A number used, in conjunction with the IP address, to indicate one end of an Ethernet conversation. Some port numbers are reserved for particular services. The port number identifies what type of port it is. For example, a server listening for HTTP traffic listens on port 80. Port numbers range from 0 to 65536, but only port numbers 0 to 1024 are reserved for privileged services and designated as well known ports. For more information, see <http://www.iana.org/numbers>

PTP

Precision Time Protocol, IEEE 1588. GPS-triggered time synchronization protocol with sub-millisecond accuracy.

PPM

Parts Per Million.

Pps

Packets Per Second. The measurement of activity in a local area network.

QoS

Quality of Service. A measure of performance in a data communications system, which may comprise of one or more metrics. In networked-based systems typical QoS metrics include latency, jitter, throughput, and loss. QoS provisioning mechanisms are used to ensure that the system's performance meets the target QoS goals as defined by the relevant QoS metrics.

QPSK

Quadrature Pulse Shift Keying. A digital modulation scheme that conveys data by changing, or modulating, the phase of a reference signal (the carrier wave). See [FSK](#).

QRRC

Quaternary Root Raised Cosine. A base-band modulation that allows almost twice the data rate as PCM/FM in the same RF band.

RAM

Random Access Memory. Memory that is 'byte addressable' and provides direct access to any location on the chip. The contents of any byte can be read or written without regard to the bytes before or after it.

RARP

Reverse ARP. A protocol that retrieves the IP address associated with a given MAC address.

Ratiometric

In electronic or electromechanical systems, it refers to the output voltage as a ratio of the supply voltage. For example, if the input voltage is doubled, the output voltage is doubled.

RCC

Range Commanders Council. The RCC is part of the U.S. Government. See [IRIG](#).

RDAU

Remote Data Acquisition Unit.

Return code

Represents the success condition of a tool. '1' means success; '0' means failure.

RFP

Request for Proposal. Invitation for suppliers, often through a bidding process or invitation to tender, to submit a proposal on specific commodity or service.

RFQ

Request for Quotation. A process where suppliers are invited to bid on specific products or services.

ROM

Rough Order (of) Magnitude estimate. An early cost estimate used to give a rough estimate of what the project will cost to complete.

ROM

Read Only Memory. Memory that permanently stores instructions and data. Its content is created in the last masking stage of the chip manufacturing process and cannot be changed. Although EPROMs, EEPROMs, and particularly flash memory, are the kinds of non-volatile storage one hears about more often, ROM technology is mature and inexpensive.

RMA

Return Merchandise Authorization. An RMA is the official authorization from Acra that it will accept product to be returned from a customer site. An RMA is typically granted by Acra when there is a problem with a product which necessitates its return to Acra for repair, rework, or replacement. RMAs are granted by the Applications Department at Acra.

RNRZ-L

Randomized Non-Return to Zero Level. See [PCM Codes](#).

RTP

Real-time Transport Protocol. Transport protocol running over UDP/IP, used for real-time applications.

RTSP

Real-Time Streaming Protocol. An application level protocol for controlling the delivery of data with real-time properties. RTSP is known as the Internet remote control since it provides a mechanism for users to PLAY, PAUSE, and REWIND selected streams of data. The RTSP protocol only defines how to command real-time streams, it does not define how those streams are delivered across the network.

RX

Receive. A communications abbreviation for receive. Contrast with [TX](#).

RZ

Return to Zero. See [PCM Codes](#).

SDRS

Structural Data Recording System. Similar to SUMS.

SHM

Structural Health Monitoring. Used for civil engineering originally (bridges, buildings) and then airplanes.

SINAD

Signal to Noise And Distortion ratio.

Snarfer

Primarily a Curtiss-Wright word for a bus monitor that stores traffic and tags (such as time) in a FIFO. For example, as per [IRIG-106](#) chapter 8.

SNMP

Simple Network Management Protocol. A widely used network monitoring and control protocol. Data is passed from SNMP agents, which are hardware and/or software processes, reporting activity in each network device, such as a hub, router or bridge, to the workstation console used to oversee the network.

SOQPSK

Shaped Offset Quadrature Phase-Shift Keying. See [QPSK](#).

sps

Samples Per Second.

SRAM

Static RAM. A fast memory technology that requires power to hold its content. Static RAM (SRAM, S-RAM) is used for high-speed registers, caches, and relatively small memory banks such as a frame buffer on a display adapter.

SPHM

Structural Prognostic Health Monitoring. Similar to PHM.

SSS

Smart Source Selector. A Curtiss-Wright technology where elements of link power, signal-to-noise ratio, best bit selection, and best data selection are used in diversity combining.

STP

Shielded Twisted Pair. STP is used in noisy environments where the shield around each of the wire pairs, plus an overall shield, protects against excessive electromagnetic interference. Contrast with [UTP](#).

SUMS

Structural Usage Monitoring System. Mostly used for aerostructures/wings on airplanes.

Switch

A device that can forward Ethernet frames to their destination.

Sync word match tolerance

The number of bits (0-63) that can be incorrect and the sync word is still considered a match.

TATEM

Technologies And Techniques for new Maintenance concepts. EU study with 60 companies under framework program.

TCP

Transmission Control Protocol. A reliable transport protocol, which ensures that all data arrive accurately and 100% intact at the other end by allowing for acknowledgments and retransmissions of lost packets.

TCP/IP

Transmission Control Protocol/Internet Protocol. This de facto Unix standard is the protocol of the Internet and the global standard for communications.

TDM

Time Division Multiplexing. A process by which there is a strictly defined schedule that controls when a node can transmit on the bus.

TDMA

Time Division Multiple Access. A process by which there is a strictly defined schedule that controls when a node can transmit on the bus. Multiple nodes may access the bus.

Telemetry

The science of gathering information at some remote location and transmitting the data to a convenient location to be examined and recorded.

TFTP

Trivial File Transfer Protocol. File transfer protocol that runs over UDP/IP.

THD

Total Harmonic Distortion. A measurement of the harmonic distortion present in a signal. It is defined as the ratio of the sum of the powers of all harmonic components, to the power of the fundamental frequency.

THUMS

Engine HUMS (T=Turbo fan/shaft/jet). See [HUMS](#).

TMATS

TeleMetry Attributes Transfer Standard. ASCII file metadata format for PCM related metadata.

TX

Transmit. A communications abbreviation for transmit. Contrast with [RX](#).

Typical

Error at 25°C.
Contrast with [Max](#).

UDP

User Datagram Protocol. An unreliable connection-less transport protocol which doesn't provide a guarantee that packets will arrive, or that they will arrive in the order in which they were sent. UDP is widely used for streaming audio and video, voice over IP (VoIP), and videoconferencing.

UTP

Unshielded Twisted Pair. A pair of wires that are twisted around each other to minimize interference. Contrast with [STP](#).

VDC

Volts Direct Current. Electricity whose polarity is constantly the same polarity.

VHM

Integrated Vehicle Health Monitoring. Used for NASA space vehicles originally. Relies on extensive network of sensors built into the vehicle.

Viterbi Equalization

A method of taking advantage of known inter-symbol interference inherent in some modulation schemes such as PCM/FM to improve bit error rate.

VHUMS

Vehicle HUMS. See [HUMS](#).

VL

A Virtual Link defines a preconfigured unidirectional connection from one end system to one or more destination end systems in an ARINC 664 Part 7 network.

VLAN

Virtual Local Area Network (Ethernet). A logical subgroup within a local area network that is created via software rather than manually moving cables in the wiring closet.

 V_{rms}

Volts Root-Mean-Square. The root-mean-square (rms) voltage of a sinusoidal source of an electromotive force: V_{rms} is used to characterize the source. It is the square root of the time average of the voltage squared.

 V_{p-p}

Volts Peak-to-Peak. The difference between the largest voltage in the signal and the lowest voltage in the signal.

WLAN

Wireless Local Area Network (IEEE 802.11). A local area network that transmits over the air typically in the 2.4GHz or 5GHz unlicensed frequency band.

XdefML

XidML Definition Markup Language. A published (on www.xidml.org) validation schema that can optionally be used in conjunction with XidML to allow vendors to specify constraints for their XidML instrument definitions.

Xid

eXtensible Instrumentation Definition. Old metadata standard, now replaced by XidML.

XidML

eXtensible Instrumentation Metadata exchange Mark-up Language. A published metadata schema for how telemetry systems are configured. XidML supersedes XID and Curtiss-Wright's XML. It includes hardware, packet, and processing setup information.

XHUMS

Experimental HUMS. See [HUMS](#).

X-Tools

Versions of some of Curtiss-Wright's software tools, such as X-Setup, X-Report, X-Translate, and X-Validate; introduced in an attempt to popularize XidML.